#731605 ①

11-15-1963 set CM over 1" steel rod.

section corner. 16-17-20-21 Haverhill 107-13.
4-1858 Hunter P54 No 78 L 21.
used corner - set 1/16 east M&L 19.75. 1303.5

5-1894 Jr Fraser P549 No 507 L 17. P Robinson.
Corner gone. reset corner with stone, John Mahon.
Mr. Robinson where the corner stood in E-W fence but
couldn't say as to E & W. so meas L 1/4 17 to L 1/4 16.
and set stone as corner under fence, gone perp meas.
- meas east 39.85 3/4 (2630.60
- meas west 39.92 3/4 (2635.2
- 16 North set stake M&L 19.87 1/2 (1311.75 - over -

– also set stake between E 1/4 17 and 1/16 L N&L 9.93 3/4.

T. Hunter June 1877 Field Book 4 p. 176-177 unrecorded Survey
Something used as Sec Cor. Shows 6 Ts & Means East 19.75 - 19.75 To 1/4 Cor 16-21

6-1896 Hunter P 602 no 547 L 21. John R Daly.
found stone set by N Fraser P 549.
– 16 each set stone 2x10x24. N&L 19.93 (1315.38

limestone found and used as corner.
11-1963 J Kerr. set C/M. over 1" steel rod
corner lies 2 feet northwest of fence corner & fence E, W, L.
– Meas south 2626.8 to rod set N&L
11-20-72 found 1/16 stone each, offset carefully 100' south at 1/16 and sec. corner. Meas betw. 1314.0 Cent line & Meas each. Could not find 1/4 16-21 set stone and witness
Lee 1/4 16-21.

Gov't Notes W.B. Yerby 1853 #731605 - (2)
80.00 Std A Std cor post to Std 16, 17, 20 & 21
Bur Oak 15 in 5 to Fizl/Ks
Made A Trench
11/14/89 FD CIM IN GOOD COND. NAILED SIGN
TO CORNER POST