/ 5-17-74 SET C.I.M. (Shorty) No rod set because of concrete base
out made 2-21-74
6/1/90 C.I.M. gone 9/18/92 V.F. set ½" pipe CARD # 1

1/4 Corner 17-20 Haverhill 107-13
#731704

5-1878 Hunter P 342 No 336 S 20 C Wilson
found orig stake in mound and NE B.T stump and
set new stake in mound. SEBT standing
-16 west found 4" poplar tree at corner location
marked tree & set stake near M&L 19.92 13/4 72
-16 center NW 1/4 20 set stake M&L 19.88 13/2 08
on N-S 1/16 line.

---

5-1894 H Fraser P 549 No 507 S 17 P Robinson.
found govt stake & SEBT standing.. John Mahon
drove white cedar stake and stone 6x8x1 by its side.
- over -

-16 north set stake M & L 19.91 3/4
also stake M & L 9.95 7/8 above 1/16 and center 17
- meas east 39.92 3/4. 2635.21.

---

3-1900 W Fraser P 661 no 588 & 20 M Fitzgerald
John Boies.
found corner P 549. 1317.36.
-16 east set stake M & L. 19.96. which came 1 link south
and 1 link west of corner fence post.
-16 south drove iron stake M & L 19.87. (1311.42'
-16 center NE 1/4 20 drove iron stake intersection
staked line for fencing south.

---

Corner now in complex of deep U & conservation gully & dam.

---

April, 1858 T. Hunter Fg. 55 No. 79 shows 1/4 Post with 2 T S
(N 79° E 60 lks. X-S 62° E 121 lks)
Meas. South 39.45 chs.

CARD # 2

1/4 CORNER 17-20 HAVERHILL 107-13

#731704

5-3-1974 Ran the N-S 1/4 line Sec. 17 - South - Intersected it with the E 1/2 of the South line sec. 17. Found w Fraser's stake at the 1/16 corner E. of South 1/4 cor. 17. Set a "shorty" C.I.M. at the corner locating & took two references

Camshaft North 125.82' (on N-S 1/4 line Sec. 17)
120 d spike South 36.18 ( " " " " ) 17

Gov't Notes W.B. Yr-by 1853 Eas Random 17+20
40.00 Std Stamp Std post
West on true line between Std 17+20
(over) 8° 11' E

40.03 1/2 STI A STI post
Bur Oak 15 in N 80 E C1 1/K5
Bur Oak 12 in S 62 1/2 E 122 1/K5
6/1/90 Co. Surv. found cim gone found witness chainshaft north of corner in good cond.
9/18/92 Vince Fangman set 1/2" pipe/cap at county computed location
Rp's 30d spike in 10" willow ENE 22.01'
30d spike in 6" boxelder SSW 6.99'
30d spike in 6" boxelder WSW 12.65'
monument 26' north of corner past to fences S-E-W (found ~~Hoey~~ Co. trav pt creekbank gone)