11-29-1963 set C/M. in place of orig limestone. ①
section corner. west 18-19 Haverhill 107-13
east 13-24 Cascade 107-14.
8-1876 Hunter P 303 no 298 S 24 L Dodge, R Smith.
No mention of corner, only stone written on plat evidently
later caption - Meas west 30.07 3/4 then 10.02 1/4 #731805

1-1878 Hunter P 328 no 322 S 19 Geisinger, Newton
found orig corner standing by fence corner. S E B T
standing stumps of N E & S W trees altho within 2 lks
accepted stake as corner & left as is... No meas.
Note 8-1876 P 303 no 298 S 24 for Dodge Russel.
stone captioned as corner. (clearly not from survey P 303
-over-

limestone by fence corner found and accepted as sec cor.
11-1963 set C/M in place of stone.
Corner lies 1.5' NW of corner post of 4 way fence.
- center 24" red oak ~~4.0~~ 4' W of 5 1.5 to Center of Tree
-16 west run line set ½"x24" rod M&L 1316.4.
rod lies 2.8' north of E-W fence, no N-S fence.

3-22-1880 T. Hunter Bk. 5 P.108 Sec. 24 Cascade
Shows 4 B.T.'s (possibly orig GOV'T.) P.38 Sec. 19 Hayerhill - 1878
West in this 1880 survey 40.10 To stone at N.4.24
Also Shows 1/16 ~~Stone~~ South as ~~Stone 4 x 4 x 24~~ 20 lks E of Tie
at N 4°E 49 lks To 3rd fence Pgt Wrong - Stone at Center 24
No Mon T. To 1/16 South. from End of wire fence.

Section corner West 18-19 Hawk Hill 103-13
East 13-24 Creek 103-14

12

#731805

Gone No.

30.00 Set post corner 4 sides 13-18-19-24

Black Oak 5 N 25 W 52

Black Oak 6 W 2 W 262

Black Oak 14 S 72 E 97

Black Oak 12 N 1 E 274

5-9-84, West 18-19: Found CIM standing, now 1.1 South of the corner post to fence N-S-E-W. Old c.p. gone 24" Oak SW 4.0 entirely gone - no trace. Found 4"x7"x13" limestone on ground SW of the CIM. Possibly original stone dug out when new c.p. put in

(over)

RP's:

MHD SRP in East side 24" Red Oak SSW 8.68

MHD SRP in North side 30" Red Oak WSW 44.47

MHD SRP in NW side 14" Red Oak SW 46.96