updated corner office 5-14-1974 #731809 (1)

6-22-1964 set C/Mon 1"x12" disc from rug stone.
5-1-74 found stone Top of Mon. broke off Mar. 1973 WHKS

1/4 Corner Center 18 Haverhill 107-13

8-1871 Perry by Hunter & 187 to 198 S 18 MS Hydee.
set oak stake in road at inters lines
- Meas west ~~38.99~~ 38.89
- Meas north 20.00 then .5 then 19.50 to corner
set from B tree stumps with marks plain.

11-12-1888 Hunter Capture above survey.
found center 18, 1/16 north and N 1/4 18.
at center 18 drove short stake well down with stone on top.
also found same corners on west line 18, W 1/4 - 1/16 N and NW 18.

- over -

8-1893 H Fraser P526 No 491 & 18 P Gaffaney, Potter
found stone set P 187 (Caption)
-16 east set stone 6x6x26 M & L 20.05
fd - 1/16 Stone May 1, 1974 - placed 3/4" rod riser

---

corner found and used many surveys, 1" pipe riser
6-22-1964 set C/M once 1" x 12" iron rod.

Spud. power pole WSW 24.68.
" tele pole. Gone 5-1-74 NE 52.73
cross conc headwall. 5-1-74 31.68 NW 31.65
" " " Gone 5-1-74 NE 32.87.
punched cross east end galv culv drive WSW 112.1.
5-1-74 Dug down beside C.I.M. - found it to be over two stones. Reset a new C.I.M. over the stones

R.P's
Bent over "crossed nails" west side P.P.# 39231 Sc. 24.35 Center street
E. rib (flange) edge tele. box. SW. 30.3 Name sign NW. 80.6

Center 18 107-13 HAVERHILL #731809 (#2)

5-78 Dug up the cor North of cen 18 107-13
- found rotted wood - (post) West
of T-Bar set as present the cor.
R P's Southerly T-Bar E.S.E - 7.5
Nail on SE side tele pole N.W - 45.4'

4-78 M.H.D meas 2565.50 W to CIM
SEE Survey in Blue Book @ Center 13 Cascade

8-12-1980 The [redacted] Center 18: Took additional reference in case of road construction: Set iron 185.85 South of CIM and on line to iron by corner post 626± South of the Center 18
Reference to iron 185' South: (over)

CSD in pp # 34232 SW 4.4
center anchor bolt where it goes into the ground SSE 2.25

April, 1864 P.C. Compton Pg. 80 No 120 used Center Sec. Set 1/16 East (No. Meas.).

10-17-83, Center 18: Found remaining 2 sections of Kerr CIM over iron rod. Removed CIM and set a new one in it place - location checked with Ed's ties taken 6-29-83 (See C.R. 125 Book)
RPs: 1" sq by 30" pipe/cap (down 6") 70.03' South and on line to concrete nail in bottle cap beneath number plate in pp # 34232
CSD in NW side power pole NE 58.17
corner in ℄ road North and 9.7 South of ℄ E-W rd

10-17-83, 1/16 North: Set a 1" sq pipe/cap from reference taken 7-5-1983. Corner came just East of
(cont).

#731809 (3)

Center 18, Haverhill, 107-13

10-17-83, 1/16 N cont: W'ly edge South culvert apron (W'ly culvert of 2). Culvert in driveway running West. Corner 18± South of ℄ driveway. RP's!

- 1" sq. by 30" pipe/cap 69.66 West and on line to CSD in pp # 342377
- Chisel cross in W'ly edge W'ly driveway culvert E. 1.42

7-27-84, Center 18: Set a 10" CIM over the CIM in place in new blacktop on CR 124 Also checked with 1983 transit ties.

"731809"F CENTER 18 HAVERHILL 107-13
FOUND CIM AT SURFACE OF 48TH ST NE (CR 124)
CORNER FALLS 9.7' S OF CHD PI IN ℄ CR 124 (1" SQ PIPE W/CAP)
AND IN ℄ OF HADLEY VALLEY RD NE.
CSD IN PP # 23067 NE 58.26 (58.17)