3-4-77 Set a C.I.C.
11-17-78 Mike Klemschmidt from WHK reported C.I.C. gone - tells me left Rebar from RDC

section corner west 19-30 Haverhill 107-13.
10-14-86 set C.I.C. / P² east 24-25 Cascade 107-14. #731905

10-1874 Hunter P300 no 295 L25 R Smith, H Messenger
and 6-1876
found stake near corner of field which proved incorrect
after finding stump of LW BT still plainly marked
- also found stumps NE & NW Birch but so far away could
not be considered reliable as LW one reset corner from LW BT.
- Meas West 39.66 2617.56
corner came in wet sloughy ground overgrown with willows

8-1876 Hunter P303 no 298 L 24 L Dodge, R Smith.
found stake set P300 no meas

- over -

12-1900 2# Fraser P 700 No 616 S 30 107-13
Could not find corner in wet lands. E½ S 25 107-14.
- Meas W¼ 30 to W¼ 19. set midway. 39.73.
altho on town did not set on line, found likely stump
of NW CT which set corner midway N & S. and
-16 west reset corner with stone & stake from 2 1/16 corners
running line N¼ 25 to NE 25 to be M&L. 1978
proving both corners. the west set 19-30 and 1/16 west. 1305.48
- Meas east 12.68 chen 7.50 chen 18.00 to N¼ 30
drove gas pipe & set stone 2' long by side. came in line
fence north and. 21½ links south of corner past. 1.5' W Fence

Karr reset corner with 5/8" x 6' rod packed in stones
by line from west over 1/16 stone found. set steel fence post S .6'
corner comes in wet lands, south of E-W fence. Could not find pipe.

Section Corner West 19-30 Haverhill 107-13 ②
#731905
East 24-25 Cascade 107-14

2-18-77 Doubled line and measure from ¼ Cor 24-25 over the 1/16th East. This point came .66' West and 1.2' N. of Kerr iron. Dug 8'x8' centered on the point. Found what is possibly the remains of Will Fraser's stone (about 4"x6") standing on bedrock 2' deep, 1.5N and .6' West of Kerr iron (removed). Also dug for the corner post 21½ lbs. Nail mentioned by Fraser. Found nothing.

3-1-77 Accepted corner at the location of the piece of stone found. Set a C.I.C. /24" p². Corner came 5' South of the E-W fence and in line built the fence North.

R.P.'s CSD NW side 4" Blazed Elm NE 46.40
Spike in E side 4½" Birch NNW 18.93

Pipe Cap Epic 79 11-27-79 Visited Corner R.P.S 1977 GONE

Sept. 1858 T. Hunter Pg. 56 No 82 shows Sec. Cor.
used Corner in Survey of N ½ Sec. 25 10N-14W
Meas. South 39.72 Chs. to ¼ Post.

Bore Notes,

30.00 Set post ... to Bottom 19-24-25-30

12 - Ork 14 N 3¾° W 7/6 Lks

12 - Ork 10 D 1½° W 13 " "

12 - Ork 14 D 4° E 12 " "

12 - Ork 12 N 3½° E 7/6 " "

10/14/86 FD ¾" RE-ROD RESET FROM 3-1-77 REFERENCES BY MIKE KLEINSCHMIDT IN 1978. DROVE TELSPAR PIPE WITH CAST I C OVER THE RE-ROD

SPIKE & CSD IN N. SIDE 6" POPLAR WNW 25.37

SPIKE & CSD IN W SIDE 6" ELM NNE 25.42

FENCE ON GROUND NOW BUT COR APPROX 2' W OF FENCE N & 8½' SO OF E-W FENCE