#731906 Grid #1

1/4 corner West 1/4 19 Haverhill 107-13
East 1/4 24 Cascade 107-14.

4-1872 Hunter P196 No 206 L 19 O Whitcomb
found stake standing at corner of fence, tested B tree

1-1878 Hunter P328 No 322 L 19. Geisinger, Newton.
found stake at fence corner P196, No meas.

8-1876 Hunter P303 No 298 L 24 L Dodge, R Smith.
found org stake standing tested NW BT, No meas

3-22-1880 T. Hunter T.H. Book 5 p.108 Sec 24
indicates ~~No Stone North as Stone 4"x8"x24"~~
Wrong Stone at Cor 24
No meas

over.

corner post accepted as corner. - iron pipe by post declared as corner - Dr Wellner tore it out setting new master type corner post - corner now small rod on east side corner post if any corner at all. sharp slope, east to west and from north, very brushy, poison ivy briars etc.

-B79P60 9-1959 run line west to center 2611.44 set 1/64 at 1/2" rod 632.86 (B68P73) and 1/16 at 1305.72 (B68P73) this survey run line north 2627.34 found stone with cross in very brushy hedge row set 1/2" steel M&L 1313.67 very near M&L
- same survey run line north from 1/16 west. total north 2628.9. set rod at 1314.45. 3/4" pipe 3-6-71 ℄ shows stone 4"x4" top
3-6-71 3/4" pipe on E. side of treated corner post.

#731906 Card#2

1/4 Corner	West 1/4 Cor.	19	Haverhill	107-13
	East 1/4	24	Cascade	107-14

W. Fraser field book #9 p. 83-88
at "D" W/4 19 found stake & B.T. set new stake and stone 17x15x3
Meas. South 39.73 To Section Corner set midway but not on Line.

4-10-81 : Found pipe standing between two posts at corner to fences North and West.

4-10-81 1/64 West : Found 1/2" iron under E-W fence on the South ~~North~~ side of the driveway.

Dear Mrs.

Here is your order for

Bur Oak 14 N 1 E 358

Bur Oak 14 N 36 W 160