6-29-1961 set C I M over iron set by McGhie M&L.
5-6-1974 dug with Tractor Found nothing — Reset C.I.M. over rod. ①
1/4 corner 20-29 Haverhill 107-13
3-1900 2t Fraser P661 no 588 d 20 M. Fitzgerald #732004
John. Boier.
set stake on north side fence past M&L 39.96 (2637.36
-16 east drone iron stake M&L 19.98 (1318.7
corner used for line north to set temp stake ac Center 20.
6-1870 Perry P180 no 191 found stake standing in mound on fence.
west 40.60.
McGhie
set rod M&L indefinate corner ac SW Cor 20
did not look for iron at 1/16 east
6-1961 J Key B80 P64 run from C I M set at Sanders corner SE 20
west found rod set by McGhie above. M&L 2635.2 to nail in tree
ac [redacted] S.W. 20
— over —

6-1961 J Kerr.

run line accepted corner as set.

set C/M.

Sp	power pole	NNE	110.8
"	gate post	SW	93.35
Center blacktop road		S	211.6

stone at SW corner 20, not found or recorded for 1/4 cor 29 1/16 iron each should be carefully searched for. SE cor 20 not positively found either. difficult situation.

– 1971 – did dig and search for Hill Fraser 1/16 iron in area of 1/16 cor now in place. found no sign of iron set

---

May, 1859 T Hunter Pg. 60 No 56 Shows 1/4 Post.
1/16 East 23.02 chs m&L to Sec Cor. 1/16 south 20 chs. m&L to Cen Sec 29
*See Survey For breakdown in S.E 1/4 20 & NE. 1/4 29

Gov't Notes W.B. York 1953 East Random 20+29 (2)
40.00 Set ⌀ tramp Std. post 1/4 20-29 # 732004
West on true line between Std 20+29
8°44' East
40.01 Set ⌀ Std. post in Mound of Earth and
Set deposited charcoal mark trench and
pits, planted Osange Orange Sticks N+S of
trench
10/31/89 FD CIM DOWN 12" IN E 36TH AVE
NE. RP's
170.26' SOUTHERLY TO HAVERHILL AZ
7.5' NORTH TO E OF DRIVEWAY WEST