X 3-22-77 Set CIC #732005 (1)

section corner 19-20-29-30 Haverhill 10-1-13.
6-1870 Perry P180 No 191 SW¼S20 CC Wilcox
found org stake standing in mound
-16 north set stake M&L 19.95 (316.7
-16 east " " " 20.00 (320.0
-16 center SW¼ 20 set stake M&L 19.94 (316.04 on N-S ¼16 line.

4-1872 Hunter P196 No 206 S19 O Whitcomb B-1 P-12
found stake standing in mound in fence
- Meas north 39.90 to org corner. 2633.4
- " west 40.30 " " " 2659.8

1-1878 Hunter P328 No 322 S19 Geisinger, newton B-3 P-30
stone marked on plat - may not have used.
- Meas north on plat 39.9½ to "stake" then 39.79½ to Sw cor 2634.39 2626.47 - over -

9-1891 2 Yor Fracer P 456 No 440 L 30 John Holo
No mention of corner used - survey in L E¼ 30
Caption Yr Fracer 5-1894 below - could not find Hunters
stake but as Hunter said it came under fence set stone
6x8x18 by meas from ¼ 29-30 and NE cor 19 (a stone
in center mound) line short 43½ lks if divided equal would
be 39.85½ (2630.43 - and under N-5 fence as recorded
corner not divided equal earlier survey

3-1900 Yr Fracer P 661 No 588 L 20 M Fitzgerald, J Brier
B-9 P57-F
found stone set above caption. (Claims now stone set by meas
between ¼ 29-30 and ¼ 19-20 not as above. - Meas north 39.91½
2634.4
then 39.79½ to NE 19. and under fence.
2626.7
- Meas east 39.96 to stake by post set M & F
2637.36

11-1959 McGhee could find stone. No wash, no log post
they drove nail in hopeless tree as corner 2634 from ¼ 19-20.
Blazed 15" tree SW 5.0 - Blazed 12" tree NW 8.0. corner may
still be there.

#732005

Card # 2 19-20-29-30 Haverhill 107-

(2)

6-15-1970 Co surv. Meas carefully on slight ridge (E) from pipe set by Mc Ghie as 29-30 north record meas 39.91½ (record 39.5-1½) 2634.4 which came exactly opposite as near as could tell without transit of nail set in tree by Mc Ghie as corner – boulder tree a massive 2½ to 3' knarly based wire wrapped tree – dug some soil from tree base and probed extensively, west edge of tree where nail is seems to be only true portion of base south, roots under tree are unbelievably heavy & thick impossible to probe effectively also ground slopes quite sharply north for some 40 feet with cattle trail on west side tree. Stone may be gone entirely. Nail should be accepted until proven different (by digging and chopping out tree. Cattle road south about 8' to South

over.

11-16-72 dug around bottelbrush tree with nail set in at corner 2 to 3 feet out and 2'+ deep and cut roots until tree fell to the ground exposing its entire underneathand all ground below there was no sign of stone nor had any stone ever been there. RP to nail in tree

5.5 WSW to 16 D nail in blazed oak 12" N side.

9.0 NW to 16 D nail in blazed 10" oak N side

probed entire area from hole and surface - corner stone gone unless its clear out of local area.

Section Corner 19-20-29-30 Haverhill 107-13 (3)
#732005

3-22-77 Drove a C.I.C. /30" p² on the corner at double the line and measure from the NE Cor 29 over the N. 1/4 29. Corner came 1' W. of the N-S fence.

R.P.'s Sp. & CSD W. side (up 6') 6" blazed Burr Oak NNW 50.15

Spike NW side 15" Box Elder with old blaze SW 5.03

Spike in N. side 11" Box Elder NW 8.63

Gov't Notes W.B. 1/2 bk 1853

80.00 Set a set cor post to set 19, 20, 29, 30 in mound of Earth and set, deposited Charcoal Made trench and pits planted Osage orange seeds N.W. - S.E of trench