1 4/16/87 ~~SET CIC/P²~~
8/21/92 RESET CIC/P² / found tony in error corner (1989) ①
not set where he wanted #732006

¼ corner 19 - 20 Haverhill 107-13

4-1872 Hunter P196 No 206 S19 O. W Whitcomb
found orig corner in mound just east of brook.
- Meas south 39.90.
- Meas west to center 19 40.65 set centers lines.

6-1870 Perry P180 No 191. SW¼ S20 C C Willcox
found orig corner standing on east side of and near to brook
-16 south set stake on side hill N&L 19.95 (B 11.75
-16 east set stake N&L 19.87½ to center set P55

1-1878 Hunter P328 No 322 S 19. Gessinger - new lot
corner not mentioned - shown as stake
- Meas North 39.79½ - south 39.91½. - over -

5-1878 Hunter P 342 no 336 S 20. C C Willard.
found ~~stake~~ or. E 1/4 post in mound by corner post of whitcomb fence.
on east side of brook. (4/19-20)
-16 east found corner set P 180 M & L. 19.87 1/2. (1311.75
-16 north set point M & L 19.89 as near as possible
from offset of several chains east - line rough & brushy.

3-1960 H Fraser P 661 no 588 S 20. M Fitzgerald, J. Boier
found corner as recorded. P 342.
- meas south 39.91 1/2
- meas north. 39.79 1/2. run line north as in P 342.

6-1958 J Kerr B 73 P 32 run east-west 1/4 line carefully.
set rod by terminal corner post as corner. Could be near, hard
to test as N-S lines not M & L & very brushy.

Govt Mons W.B Yr by 1953 19-20 10-13 (2)
#732006

40.00 Std n std post in Mound of Earth and Sod, deposited charcoal made trench and pits planted Osage Orange Std East and West of trench.

4/5/89 DUG FROM 3.5' So. TO 8.5' So OF TOM FERGUSON T.N. & 2.5' E & 2.5' WEST OF T.N., TOM'S T.N. IS UNDER NEWER N-S FENCE 42.5' NORTH OF THE BASE OF A DAM RUNNING E-W across THE BROOK CALLED FOR BY T. HUNTER & ROBERT PERRY. WE DUG 2' 8" DEEP TO NATURAL CREEK BOTTOM. WATER FILLED UP SO I COULDN'T GET A LONG LOOK AT THE BOTTOM. IT WAS GRAVEL FOR ABOUT 1.0' DEEP THERE WAS 8" TO 10" OF FROST DOWN AT ABOUT A FOOT DEEP. THE CENTER OF THE CREEK IS ABOUT 13' WEST OF THE FENCELINE. 5.43 SOUTH OF TOM'S T.N. WOULD BE PRORATED POSITION JOHN KERRS 1/4 LINE FROM THE EAST WOULD ABOUT 1.4' SOUTH OF THE PRORATED POSITION. T. HUNTERS KINK IN THE N-S SEC LINE Over

Cont.
WOULD BE 9.63' EAST OF A STRAIGHT LINE THIS WOULD BE 1.5' EAST OF TOM'S T.N. & N-S FENCE, THERE IS A FENCE ± 250' WEST THAT LINES WITH THIS AREA. THE OLDER FENCE NORTH LINES WELL WITH THIS NEWER PIECE WHICH WAS CONSTRUCTED AFTER THE DAM SITE WAS FINISHED. WE FD NO SIGN OF J. KERR IRON OR POST HE SET IT BESIDE, NOR ANY OLD POST SPOT OR EVIDENCE OF STAKE, EVERYTHING MUST HAVE BEEN TORN OUT IN CONST.

4/6/89 SET C.I.C./p² @ PRORATED WILL FRASER MEASURE AND KINK OF 9.56' EAST OF STRAIGHT LINE, COR. IS 1.5' EAST OF N-S FENCE & 42.5' NORTH OF THE BASE OF DAM Rp's

PUNCH MARK IN 7th RIB BACK FROM END OF 24" C.M.P. IN DAM WSW ~~34.45~~' ± 39' (1992)

N.W. COR. OF Conc. CATTLE TANK SLAB N.E. ~~42.25~~' ± 42' (1992)

CENTER OF CREEK WEST 15'

SIGN & POST WEST 1.0'

5/30/90 FD C1C/p² IN GOOD COND.