10-25-1963 set C/M over iron (1)

#732009

1/4 corner Center 20 Haverhill 107-13

4-1858 Hunter P55 no 79 NE 1/4 S 20.

set corner - meas east 20.00 - north 39.45.

6-1870 Hunter-Perry P180 no 191 SW 1/4 20 C Hillam

found corner set P55.

-16 west set stake M&L 19.87 1/2 (1311.75'

-16 center SW 1/4 20 set stake M&L 19.94 on N-S 1/16 line

5-1878 Hunter P342 no 336 S 20 C Hillam

found 1/16 corner west M&L. 19.87 1/2.

3-1900 H Fraser P661 no 588 S 20 M Fitzgerald

John Baier - own

set small stake at inters lines which came
12 links south of big post.
-16 North. drove iron stake N&L 19.87. (1311.42

6-1958 J Kerr. B73 P32.

Run east-west ¼ line after setting E ¼ N&L 2626.8.
set center rod at 2608. in center road
- set rod on E-W ¼ line, not needing center as prop cor.
- set rod either by McKhee or Kerr from d ¼ corner set at
N&L or d sec line and general line north - N ¼ 20 gone.
south on 20

10-1963 Set C/M over iron at point accepted as corner
Spike in 18" oak ENE 49.92
" " power pole NW 88.15
Corner lines with fence east (new set correctly) just E ℄ road.
C/M could now be several feet east of 2608. not definitely known.

1/4 Corner Center 20 Haverhill 107-13 (2)
May, 1859 T. Hunter Pg. 60 No. 86 Shows Center Sec.
1/16 East 20.00 chs. M & L to 1/4 Post. #732009
5/30/90 FD CIM 10" DEEP WITH SPIKE AND CONC
NAIL ABOVE