1

#732104 (1)

1/4 corner 21-28 Haverhill 107-13

used corner. - set 1/16 north M & L 19.82.

also 1/16 center SW 1/4 21. Meas north 19.83 (1306.78) east 19.72 (1301.52)

1/16 center SE 1/4 21 " north 19.80 (1306.8) west 19.75 (1303.5)

- above survey 4-1858 Hunter P54 No 78 & 21.

5-1876 Hunter P23 No 36 & 28 orig survey and caption 4-1857 and 5-1876.

found stake standing covered by Mr Canty as true corner - B tree gone.

- 16 south set Marked stake M & L 19.85 to stone 2x8x24 set at center 28. (1310.1)

- over -

6-1896 Hunter P 602 No 547 S 21. John Daly.
found stake in mound of stones described P 23.
-16 west set stone 4 x 9 x 14. with stake by side.
M & L. 19.95 1/4. (1316.86'

1909 Armstrong P 120 B. S 21 John Daly.
set iron bar de 1/16 corner betw S 1/4 21 and Center 21
set this on E-W 1/16 line accross entire S 1/2 S 21.
-16 east above 1/16 iron Bar. M & L 19.77 1/2. driven 1305.15'
-16 west set stone 3 X 10 X 14 M & L 20.03 1/2 1322.3' Center Road.

1962 J Kerr. used something as corner to reset Center sec 28 - reset stone by corner past at 1/16 west. found stone A correct size at base of brace west of fence corner. figured it was moved in setting corner fence north and set as brace base. Meas from meat. chelled reseting corner into proper place

Card # 2 1/4 21-28 Haverhill 107-13. #732104 (2)

11-1-72. Meas east from C/M as set at 20-21-28-29. from a random nail north of C/M - meas without line direct to 1/16 corner, found limestone reset by corner post with 1/2"x4' rod. on North side set in 1962 by J Kerr, stone found as anchor stop for fence brace  figured as it was rounded sign it was true corner so reset it just south of corner post. However now found true stone exact sign down 18" about 1 foot ± south of J Kerr stone, re-meas 1317.4 R 1316.86

Continued meas east along fence. drove 60 nail in S side 28"+ very old burr oak in exact fence line with fence south fastened to tree meas 1319.9 area south of fence 3' higher than north of fence with no fence north with limestone pieces all thru area making search for stake impossible. (over

at 1/16 removed stone set in 1962 and placed on top of true stone with ½" x 4' rod on north side stone. as witness centering stone east and west. did not determine if meas of 1317.4 from west q offset was true meas. wind angle start at 1:00 11-1-12. remeas line carefully on 40' offset north pulling south to 5' south q section line to continue east.
- found true 1/16 stone at 1316.9. R 1316.86.
- cont line and meas east and set 120 Ø on projected line and doubling distance, which came 3.0' west q nail in oak also drove nail in W side blazed 13" oak south 8.55
Govt Notes W.B. Yr bk 1853 East Rem Cor 21+28
40.66 Std A temp. Std post
West on true line between Std 21+28 & 8°53'E
37.99 Std A Std. post
Bur Oak 8 in W to W 22 links
marks broken