/ 6-2-75 Set C.T.M. on 5/8" x 12" rod #732404 (1)

1/4 corner 24-25 Haverhill 107-13.
5-1874 Hunter P 242 no 243 L 25 M McElligott
John Lawler.
found 3 small stakes about 3 feet east of corner
of fence. found one burned out stump answering
notes as one B.T., settler believe orig stake lost
where stakes found.
– 16 west set stake M & L 19.83½.
– 16 south " " " 19.77.

7-1874 Hunter P 258 no 258 L 24-25 Haverhill
19-30 Viola.
John Nevins – over –

found stake P 242.
-16 North set temp stake N&L 19.97
-16 east set permanent stake N&L. 19.93.
-16 Center SE 1/4 24. set stake inters lines which came. 9 1/4 lks east of fence and
24 lks south of small oak tree in fence.

6-2-75 - Found large corner post had been dug in at corner location. Dug on N & E. side as indicated in Hunters survey but found nothing. Set C.T.M. over ½" x 12" rod on section line and at prorated Hunter measure Corner lies 1.7' N of "I" corner post and 123.5' ± S of Oak in fence line N.

Govt Mound W.B. 1/2 by 1853 East Random 21+25
40.00 Std A temp Std. post #732404 (2)
West on true line between Std 21+25
9°18' East
39.97 1/2 Std A Std post
Bur Oak 10 in N 25 E 330 lks
Mark A tree

7/2/89 FD CIM AT SURFACE, E OF COR. POST OF FENCES N-E-W, PLACED SURVEY MARKER SIGN ON E. FACE OF COR. POST.