6-4-1975 Set 4" piece of C.I.M. over R.R. Spike on bed rock.
#732506 ①

¼ corner 25 - 26 Haverhill 107-13.

5-1874 Hunter P242 no 243 L25 N McElligott, found rotted remains of stake on digging John Fowler. in line fence west and 54 lks east of corner past.
- set stone 2 x 5/8 x 17.
-16 east set stake M&L 19.80½. (1307.13'
a stake set intersection lines.

5-1876 Hunter P293 no 288 L26. John Daly.
found stone set P 242.
- meas west 40.06 to temp stake set intersection lines in open farm then 19.94 M&L To W¼ 26.

— note over —

Corner area now in cut of some 4 to 6 feet at hilltop. poor fences E & W but recognizable., only reliable near way to set corner by 1/16 line east, ties questionable.

April 30, 1975 Corner location Visited by R.B. – Corner now in deeper cut in newly regraded road (cut 8'-10' now)

6-4-75 Reset corner on line from E 1/4 Cor 25 over corner put at Cente 25 and at prorated Tom Hunter measure from Cente 25 since the measure from E 1/4 Cor 25 to Cente 25 came out .63' short of Hunter's full measure

Set 4" piece of C.I.M. over R.R. spike in bedrock

Corner falls 100' ± North of field driveway on West side of C.R. #119 & 11' E ℄ of C.R. #119 and 1½' West of fence line West.

R.P.'s C.S.D. in PP # 43080 W. 50.83

Punch hole N. end C.M.P. S.W 97.95

Govt Notes W.B. Vol 4 1853

40.00 set A section post

Black Oak 6 in N 55 E 60 lks

Bur Oak 6 in S 12 W 86 lks

1/4 Cor. 25-26 Haverhill 107-13

#732-506 (2)

May, 1867 H.E. Horton Pg. 84 No. 128 shows 1/4 Cor.
Meas. west 39.94 chs. to Center 26