4-26-1962 set C/M over iron - set intersection lines
10-1972 this corner very incorrect - 1991 V.F. SET ½ PIPE WITH CAP OVER AT INTERSECTING LINES
¼ Corner Center 28 Haverhill T07-13
4-1857 Hunter P23 No 36 S28.
set stake at center, intersection lines with B tree.
(N 9° W 21 lks.) (S 48° W 155½ lks).

1-1872 Hunter P191 No 202 SW¼ S28 C Wilcox
didn't use corner but found 1/16 south Olds, Fickbick.
from B tree set P 23. - set points west to W¼ cor.

5-1876 Hunter Capton P 23.
found stake at center from stone B tree P23
set stone 2 x 8 x 24. in place of stake.
-16 north set stake M & L 19.85 1310.1
-16 south set stone, M & L 20.00 likely found stake.
-over-

5-1889 Chas Fraser p 429 No 417 & 28 Col. Williams.
run & meas line from 1/16 south 20.00 and
1/16 north 19.85 (1310.1) dug extensively and carefully
but could find nothing. set temp point for purposes
of this survey.
-1/16 east set stake & stone M & L 20.00 (2x12x20)

1962 J Kerr for Peng. dug 20' x 4' in
fence row, found nothing, nor either 1/16 corner N or S.
found file & mine signs 30" deep so run interior
lines - no 1/4 corners posative but very close.
set C/M ones. iron some quartz
- center 30" burr oak NNW 50.0 about 5' W of north.
- corner on line of N-S fence = no E-W fence.

Card #2 Center 28 Haverhill 107-13 (2)

11-8-92 set 120 D.as 1/4 21-28 on projected line from C/M at NW 28 over 1/6 stone 1316.9 east and doubling distance. ~~about 99.2 west of 1/4 28-33~~ #732809

- offset 100 west and ran south on line of random lath on rock west of 1/4 28-33 about 99.2 west of 1/4 28-33.
- found C/M now in place in cornfield at 2616.3 R 2620.2 on completing line which fell 105.5 west of C/M found C/M as set to R. 5.9' too far east to be on line 1/4 corners as set.
- future of Center 28 dangerous as in open field now and not too deep. Set rather skimpy reference as follows

50.0 5' W & N to 60 D on E side 30" oak.

75.0 NW to edge of 2nd steel fence post in random aligned picket fence running WSW'ly.

1-1972 summary of Lente 28 location.
Meas N 2616.3 R 2620.2 No meas south at this time
Corner lies 5.9" ± east of deriet line of 1/4 corner as set.
No chance of Hanten 5-1876 stone 2x8x24 being in place.
fence row now all cultivated accross old fence ridge on
quite a slope south (at least 8 or 10 % slope).
5/10/91 Vince Fangman ~~Set~~ Found Corn
Broken, Set ~~it~~ it over 1/2" x 18" PIPE
AT intersecting quarter lines