/ 11/14/89 FD 3/4" ROD IN GOOD COND. #732909

1/4 corner Center 29 Haverhill 107-13 (1)
5-1858 Hunter P56 no 81 SE1/4 S 29.
used corner (set survey no 39.)?
-16 east corner M & L 20.20 (1333.2'
- meas south. 40.20 (2653.2'
-16 Center SE1/4 29. set. meas east 20.07 (1324.62'

M'Ghie (Roger) set big iron staff by true intersections
11-28-72. offset 40' West of 1/4 20-29 C/M. for line south
offset 40' at point near 1/16 south and Cont. tindonly south.
missed above rod.
missed, corner post & fence E-W-N at 1/16 south of Center 29.
all land south common no fence.

over

Completed general fence orientation line average at 41.7' where ¼ 29-32 bound intersect exact south line Sec 29. did not pull rod or re-set corner as left this to female surveyors.

Apr. 1880 T. Hunter Unrecorded Survey in Secs 29 & 32 - Wilson & Baier
T. Hunter Bk. 5 p. 109

at "3" Center 29 — Set Stone 24"x6"x4" - q/60 set 5/16 Cor.
South at 19.92 Then 19.92 To S.¼ 29, q/50 set stake
at Center S.E.¼ 29.

6-9-76 Dug with backhoe in pasture 2½' deep to clay from 1' S of iron shaft for 13' N and from 6' E of shaft E. to N-S fence (approx 7'). Found nothing.

6-15-76 Set ¾" x 30" iron at intersecting line approx 8.8' E and 5.0 N of McGhie iron (removed). Corner 4.2 W of N-S fence. Set steel fence post along side.

R.P.'s Spike W. side Willow - NNE 83.7
Spike E side pp # 20305 NW 152.8

1/4 Corner Center 29 Haverhill 102-13 ②

may, 1859 T. Hunter Pg. 60 No. 86 shows Cor. Sec,
1/16 North 20.00 chs. m & L to 1/4 Post. #732909

(See Survey for N.E. 1/4 Sec 29