A 5-16-1974 Set C.I.M. over ½"x2' rod & stones fd (#733104) (1)

¼ corner south ¼ 31 Haverhill 107-13.
north ¼ 6 Marion 106-13.

5-1891 2has 9 raser P457 No 441 d31 Stab mins
Set stake with stone beside of stake.
corner long gone. No evidence or knowledge.
run south line 31 78.425 chs Gov R 78.70 = 5196.2
5176.05
set stake & stone on line and pop dist.
- meas west 38.56½ 2545.29 Meas east 39.86 2630.76

6-1896 Hunter P603 No 545 d6 N Hallock, J. Coe.
dedut find above corner, claimed gone N Breckenridge
many years, run section line set stake by meas only
for line south- Meas west 38.56 east 39.86.
2544.96 2630.76 -over-

Co Hwy Dept bk 277

Needs urgent examination as to location & meeting.

1¼" pipe in road at corner. origin unknown See (2)

Direc power pole # 40979 NE 74.0 ~~63.37~~

" 10" maple Gone S.E. 68.06

" brace pole 19135 # N.W. 80 ~~71.02~~.

" 12" maple Gone S.W. 53.17.

1968 road newly graded & surface widened

— Meas east 2624.28 5178.11 Meas west - 2553.83?

Check at McGhee 2630.76 5175.72 R. 2544.96 Record

Calc 2623.81 5172.49 2548.68

11-10-72. found County Nail used as ℄ 31' above.

Dist in SW side PP # 19136. S.E. 61.67

Pics in red and above pic taken 11-10-72.

Card # 2 S ½ 31 Haverhill N ½ 6 Marion. (2)
11-10-92. ran direct aerial from C/N over twsp corner to
nail set by County at S 31-32 supposed to be over orig corner.
Record west 2544.96 T.H east 2630.76 total = 5175.72 2545.29 T.F.
with ¼ corner on line at these proportionate distances
Thos Fraser 5-1891 set stake with stone beside it #933104
Thos Hunter 6-1896 claims corner gone many years. set stake
both used and found meas. to be exact east Hunter .33 chat N.
— County meas west 2553.83 east 2624.28 = 5178.11
this meas doesn't state if exact corners used not P.I.S
Elect Meas west ~~2548.68~~ (2546.5 ± 1974) east ~~2623.81~~ (2626.0 ± 1974) = 5172.49
— this elec meas to a nail set on direct line which came
4.88 north of county nail. by random eye line
summary = Corner, ¼ in place, and S 31-32 correct, would likely
lie upto 5.14 W 4.88 N

True origin of corners as shown B 8 8 & 1. 1935
by Co Hy Dept. corner assumed. set bridge spike
81.9 Sp Dec Maple NW - 54.85 Sp Dec Maple NE
Station .00, ignored S 31-32, Station of limestone and 1" drillsteel
at S 1/4 32. 52+62.8 Sp 15" Maple SE 66.6
Sp. in tele pole brace NW 44.2 Sp in 24" Oak SW 78.8
record. 2630.76 + 2619.54 = 5250.3

Station S 32-32 794 20.3 or 2657.5 from limestone and drillshaft
at S 1/4 32. (now 2640.15E).

4-29-74 Dug to find orig stone (Found Nothing) dug with Jackhammer
5-16-1974 Dug with backhoe + found 2 stones - vertical
set a 1/2" x 2' rod between the 2 stones
and a C.I.M. over all.

4/2/86 FD HEAD OF CIM BROKEN OFF

#733104 (3)

1/4 corner	South 1/4 31	Haverhill	107-13
	North 1/4 6	MARION	106-13

RP's

Co. Surv disc. W. side tele pole	S.E.	64.78
Minn. Hwy dept Control menu.	S.E.	87.20
Bottle cap. E side PP# 40979	N.E.	73.35
C.H.D disc SW side T. pole # 19135	N.W	76.88

7-1979 Shot corner in control survey (Remon. BK 1979 P.103)

Found No

Was no [illegible]

Set [illegible] 285 Ks

Roger wrote in CHD BK 88 P1

Cor. 2.2 North and 2.2 West of CHD pipe. (Cut)