N.E. Cor Sec 6 - Marion

4-1-71 Jerry-Frank

Spk & Disc in P.P.
N.E. - 62.82

Spk & Disc in Light
Pole N.W. - 74.70'

Center of Sign Post
in Conc. median S.W. - 25.96

Center of Sign Post in
Concrete Median S.W. - 89.80'

Hub N.W. 56.45

X Set CIm — April 1979 #923206 ①

1/4 Corner. 31 - 32 Haverhill 107 - 13

~~No records available, known.~~

1947
~~5-1958~~ McGhie M+L - 2621.7

set 5/8" rod. midway & on line.

Spike 24" oak NNE 74.9.

" 18" " ESE 74.0

T. Hunter 3-1878 T. Hunter BK 5 p. 43 Sec. 32 E.O. Jordan

found old stake standing

meas East 19.96 To 1/16 Stake set, 19.96 To stake set at Cen. 32

T H. Book #14 page 56 shows Tie 4.60 chains North Railroad tracks (do not know if ℄ or R/W line

Geo Notes W.B. 1/4 bal 1553

40.00 std N std. pist

Bur Oak 10 in W 4° E 1.72 IKs - 113.52

Bur Oak 7 in S 4° W 2.8 IKs

11-9-1978 Co. Surv. (Rud & K Adams DNR) found mete 9/16 rod using R.R. (rod is on N. edge 12" red oak tree)

also chd 30 from ℄ RR 359'± which is about 4' N. of rod

(38" Brass (North 4.16 E) still in place. Set small iron to hold loc.

11-15-1978 Co. Surv. fd dark spot in yellow Soil - running from about 1' deep To 2' deep at location (within 0.5') of B.T. Tie location set 1"x2"x16" wood stake (old & smashed rotted) in N. part of dark spot which felt softest with a probe. Took 2 local bearing trees. Will check on the exact location by trav. and comp. Dug 2'x6'E-W centered on Brg tree loc. The N side of the spot had 3 corners and could be the Govt stake loc.

RPs SE 6.50 in 12" Oak SE 7.15 SW 6.50 in 12" Oak SW 4.65

¼ Corner 31-32 Haverhill 107-13 (2)

#733206

5-1-1979 The County Surveyor went to ¼ Cor 31-32 to pick up plastic photo panel - then set the ¼ corner in place of ½" rod set over a wood stake as placed in Nov. 1978. Set a 16" CIP over a 1"x12" iron pipe and took ties to trees:

Spike in E. side twin 12" Oak SE 7.15
Spike in W. side 12" Oak SW 4.65
Corner ties 9' N. of fence to West and 3' W. of fence to south both of which are tied to a tree for the fence corner. Removed MC&B iron rod which was 4.0' So. & 1' West of the CIP as set.

Thomas Hunter 5/28/1872 (bk1 pg 31,32)
Found orig 1/4 post standing and tested by witness trees which were still stand.
found stake had been moved 2 lks NE
found old hole were it should stand,
with splinter of old stake in it, reset
stake in old hole. Set stakes every
40 rods east on quarter line for
fencing on a bearing of N 89° 10' W
6/1856 T.H. (pg 8, No. 14) used corner to set center
of section 31