X 10-16-72 found tree corner stone - left as we stood up (1)
6'12'90 SET C1C/P² INPLACE OF STONE
#733306
1/4 Corner 32-33 Haverhill 10-7-13.
8-1884 Hunter P391 no 382 S 33 J Williams, Hickey.
found stone set perone survey when stake and all
B trees were standing.

11-1892. Thos & W Fraser P499 no 470 S 33 Frankland
found remains of old stake with stone by side. Bros:
-16 north set stone 3'x15x26 M&L. 19.93 13.15.38
-16 center NW 1/4 33 set stone M&L N-S 1/16 line
no mark

JKen 11-14-27B-3 P34 found rotted stake east of corner
Set L stone 2"x7" bottom 18" long running to point over
remains of old stake. No Good See P.C.
-over-

1869 Thomas Hunter (railroad ties) measured South 1259' to centerline of RR tracks, and 1877' west to centerline of RR tracks

5-1957 McGhee. No Good

found 4" by long limestone 2 feet southeast of Corner fence post.

6-1969. Sanksbie - Tom Furgeson. No Good

found. above limestone 2' SE of corner post.

8" elm tree. 2 feet ± north of stone.

-16 north found 2" x 8" top ? ? vertical limestone on south side in roots of boxelder tree near fence corner of fence. south and east.

Note: See T. Hunter Bk. 5 p. 43 3-1878 Sec. 32 indicates stone on Plat - no desc. of it.

Oct 1857 John Fellows Fd 41 No. 63 show Ver South with Mes 19.71 Chs. to So. 32-33

Card # 2. 1/4 32-33 Haverhill 107-13. L#733305 (2)

10-16-72 Much doubt as to correctness of this corner
Meas from 1/16 stone to south without line (sort of "fly line")
Meas of 1315.38 seemed to fall 6' south of stone.
- found center 33 offset 20' N at 1/4 33-34 by eye on
west side of road (could be off several tenths) had to drop
to 19.7 at center - pushed bore with several p.o.t. points
and offset south .7' to get a point opposite stone
Reddily found at 1/4 32-33 at 2643.76 R2643.8
stone 19.35 corrected so center & E 1/4 33 proven correct.
as far as Frankland Bros survey concerned.
- stone found very positive vertical limestone in cleanout
with numerous small pieces either set or shattered from mainstone

set 120 D over stone edge stone down about 6".
stone 13.87' west and 5.65 south of J Kerr 1927 set stone.

Corner. 5' south of fence running west.
10' west of poor fence running south.
14' west of fence running North.

15.1 ENE to 20 D SE side 12" tree with J Kerr stone grown into South side of tree roots.

14.3 SE to 40 D on SW side 16" blazed cherry or hackberry

found at NW 33 Mc Ghee pipe 12.8 west of stone found and set.

at NW corner 33 (28-29-32-33.

seems like 1/16 stone betw 1/4 32-33 and 28-29-32-33 corner ± 1.7 south of midway and .5 E of direct line

Govt Mon W.B Yr by 1953
40.00 Std A station post
Bur Oak 6 in SCS E 222/45
mark A 1 notch

1/4 52-53 107-15
#733306 ③

6/6/90 FD STONE, FD IN 1972 WILL SET CIC/P² IN NEAR FUTURE

6/21/90 DUG OUT STONE 3X9 X 21, STONE IS NARROW AT TOP BEING ONLY 1" THICK, SET C.I.C ON 4' TELSPAR PIPE WITH STONE LYING ON GROUND BESIDE MON. CORNER IS ± 6' SOUTH OF POOR FENCE RUNNING WEST & 13' EAST OF POOR FENCE RUNNING NORTH.

RP'S
OLD SPIKE (1972) IN 13" TREE S.E. 14.33'
SPIKE IN 8" ELM S.W. 14.95'
SET SIGN & POST 1.0' NORTH

5/28/1872 Thomas Hunter (bk 1 pg 34, 32)
stake missing reset from witness
tree. Set stakes on line every 40 rods
on quarter line west for fencing. on
bearing of N 89°, 0' W
~~6/14/1899~~ 4/8/1901 William Fraser, Co. Surveyor (pg 658,
No. 586) used corner chained west 20.02½
set a stake then 20.02½ chs stake then
19.98chs found stake marked ¼ S ~~2~~ 1 lks east
of fence, drove new stake in its place.