1/ 10-16-92 found small limestone and 3/4" round rod (illegible)
should be checked
1/4 Corner Center 33 Haverhill 107-13
also Field Bk P44-45 (1)
11-1892 2 hos & Wm Fraser P499 No 470 S 33 Frankland
set temp stake at inters lines. #733309 Brae.
-16 north set stone M & L no mea given
-16 east set temp stake M & L line short 15.51'
-16 west " " " " lane over run 3.74'
-16 center NW 1/4 33. set stone M & L N-S 1/16 line
-16 center NE 1/4 33 set stake inters lines

10-16-92 found 2" square top limestone (not very long) but very vertical with 3/4" iron rod about .2' east of stone which may have been driven thru old stake. P44-45
Ran and meas due west 2693.76 R26438 (See small TF Book)
(over)

line of E¼ 33 over this iron came near exact
Considering that backsight to ¼ 33-34 set 20' N on
west edge road by eye. and 19.7' offset N used for line W.
- Corner 1.5' N of 6" cedar post of fence running E
in line row of boxelders and fence running N.
fence S not this fence at all.
- Meas N to E-W ¼ fence about 1300 which is at least
12' too far south. - corner seems to be 5' ± at least (could be 8'±)
east of N-S ¼ line using ¼ corners now in place.

10-18-72 Elet meas from ¼ 33-34 west to iron at center 33.
~~2618.6~~ +5.8 = 2624.4 = 8-19-81
Thos Tracie not book states I to H short 23½ links
or 15.51' or 2624.49 showing he did use different ¼ corner
— west of center 33 he states I to G overran 5⅔ links or 3.74
making 2643.74 to ¼ 32-33 actual Manuel Meas 2643.76 so leaved
same center 33 exact as now in place - came N-S on E line

Card # 2 Center 33 Haverhill 107-13 (2)

1-16-1973.

summary of location of corner at Center 33. #733309

- small stone and 3/4" iron (quite long evidently as to real solid) still in place. Could have been set by Wm Fraser who helped TF 1892.

Meas west to stone used by J Fraser 2643.76 R 2643.74

Meas east to CIM set by J Kerr 10-1963 2619.6 + 5.8 = 2625.4

as Jhos Fraser said this line was 23½ lks. (15.51) short 8-1981 Kerr

or Meas of 2624.49 (Fraser states he did not have position corner at ¼ 33-34

ast to being on true N-S ¼ line - it is not on line shall.

meas N ¼ 33 to NE 33 2647.35 mean 2628.33

final S ¼ 33 to SE 33 ~~2609.31~~

actual elec 2619.45 + .85 (E ¼ W of direct line) 2620 30

Center 33 as set is 8.03 east of direct line final 8.03 ¼ corner

Thos & Will Frazer meas of N-S 1/16 line of NW 1/4 33.
16 chs short or 3984 (2629.44.
Elec meas of same 2627.80 or 1.64 short.
1/16 in road. Set M&L. 1322.83 very slightly off of stone below.
(betw NW 33 & N 1/4 33).
as to final E-W 1/4 line Center as found may be very close.
as line run. 20' eyeball offset north. (Left on W edge road
set eye line west from mark 20' N of actual C/N.) stone
(5) 19.7 N at Center Iron, came out 19.35 at 1/4 32-33.
actual stones found at N 1/4 and S 1/4 33. may not have
been either one used in Frankland survey P44 little B

Oct. 1857 John Fellows Pg. 41 No. 63 - Some Meas. on S.W. 1/4 S.W. 1/4 of Sec. 33