L 4-3-73. reset nail from RPS took more RPS for corner.
NOTE: See unfinished cert 5/16

#733404 ①

1/4 Corner south 1/4 34 Haverhill 107-13
north 1/4 3 Marion 106-13.

5-1876 Hunter P292 no 287 S 34 J Lawler, J Baier
J Daly J Moriarty.
found stake in mound. left as found.
-16 north set stake M & L 19.87.
-16 west " " " 19.89.
-16 center S W 1/4 34 set stake M & L 19.88 1/4 on N-S 1/16 line

12-1937 Co. H.D. field bk 88 p.8 Sta. 159+60.9 B. dge SPK
apparently assumed Corner

Corner now 1" iron rod origin unknown - no ties

6-1949 Kerr B. 42 p. 19 - Kerr set 1" iron shaft
1.5. Le pipe as 1/4 Cor. by mons. from
North & West (1/16 Cors.)

4-3-1973. WTW—

4-3-1973 found 2 original M'Ghie references - no sign or needle dip & corner or rod set west by M'Ghie.
Next small nail on 2 RPs.

42.85 N.W. ly to spike in tele pole } these only surviving
52.55 N E ly to spike in tele pole } RPs could be in danger

54.87 S to shank & large PK in top center post.
57.4 S W ly to punch hole in W end field culv. (Iver end)
47.6 S S W ly to punch mark in lug & apron E end field culv
69.41 N E to punch mark in lug & apron on W end field culv.
6'± S S E ly to apron center black top of Co road # 9.
Reference corner not gone but too deep to register on locator.

1/4 South 1/4 34 Hartford 107-13 (2)
North 1/4 3 Marion 106-13 #733404

7-13-81 South 1/4 34: Dug with backhoe. Fd that digging had been done in the area. We scraped to clay & Fd. a mark which may be spot of J. Kerr iron a could be spot from stake used by T.H. 1876 - This spot fits with 1/16 Cor. stake North - found 7-16-81

7-28-81 Set C.I.M over a 5/8" x 18" iron at location of spot found that fits 1/16 Cor North. (pt .95. & 2.5W of nail Fd @ surface)

RP's & CSD in telephone pole NW 42.01
CSD in corner post South 63.91

Chisel "+" in clamp plate in East end of Culvert S 46.46
Chisel "+" in clamp plate in West end culvert SW 54.14

CIM is 4½' N. of ℄ Co. Rd 9 and ± 1' East of line of fence S.

LRP Nail { South 5.24 / East 6.45 } Spot { S 5.08 / E 9.03 }