6-27-80 Removed CIM

9-2-1965 CIM set by county after re-grading #733405

1972 checked R.Pi and found 1½" pipe

section corner south 33-34 Haverhill 107- } Corner 3.16 East?

10-1979 Shot CIM but this corner in question.

North 3-4 Marion 106- }

5-1876 Hunter P292 No 287 L34 J Lawler, J Baier J Daly, J Moriarty

Corner missing many years coming on stony ridge on road. - by previous personal knowledge of corner, replaced corner. a boulder 5x8x20 in line and 2 rods from southend of John Clarks east road fence, being on west side of farm.

-16 east set stake M&L 18.89 (312.74

-16 center SW cr 34 set stake M&L 19.88½ (312.24 N-S 1/16 line

4-1878 Hunter P333 No 327 L4 H Brackenridge: found stone center road P292. no mear

11-1892 Chas Fraser P499 No 470 L33 Frankland Bros

- over -

stone pulled out by "Road Hog" - found where mark of stone location was also fence post described P292.
Replaced stone in proper location. No mon or 1/16
12-1957 Co. H.D. Field Book 88 p. 7 - calls for bridge spike at corner
BK 274 P. 3
stone? found and location retained - Road now 20' cut.
C/M (dep) placed by county after regrading (9-1965)
Disc corner fence post N.E. 72.46
" W Side power pole 19054 up 3' S W 118.7
" NE " " " 19052 up 3' S E 140.5
1935 Co H.D. B 75 P 8. - Set 80p spk on line from SE cor 4 over E 1/4 cor 4
Meas d. 2584.07 - 2581.92 Dist record. - West 2605.0 then 2662.8
B 75 P. 9 - Ties: Cor. & P SE 40.1' Tel. p. # 101 - NE 36.6 to S W 33
7-27-1979 - Set 9 1/2" Stub Top [illegible] of C.HD C.I.M.
set new Mon. after [illegible] Flush with BLK Top.
VOID
Add'n Tie - Ground Wire on N. side Near P.I. - East - 48.0'

#733405 (2)

Card # 2. south 33-34 Haverhill 107-13
north 3-4 Marion 106-13

Note - discrepancy in notching of corner details.

1949 J Kerr B 42 P19. set 3/4" pipe {From North & East

Meas east 1312.2 M+L R 1312.74
Meas south 1264.8 then 1323.0 total 2587.8
Meas north 2625.3

RPs before Grading
Spk & Disc in RR SE 53.5
Spk & Disc in Tel pole NE 45.3

Unknown Location
60D spike

C H D. B 274 P3 1962.
set C I M in 1965.
Meas south 2581.38'
Meas north 2630.48 ?
52 11.86

John. 2587.8
John. 2625.3
5213.1

County 1987
2584.07

RPs after Grading
PP-SW 48.70
PP SE 40.50
Cor. to post NE 72.4L

over.

BK 75 PS-9

B 88 P 73 CoHD 1937 set iron pin from (pre-survey)
Meas south 2584.07 placed by pro rating from
south - from 3-4-9-10 north. 2642.2.
from 1/4 3-4 north 2584.07

RPs
Cor. Cp. - SW - 44.4
Tel. Pole - NE 42.4
Cr. Cp. SE - 40.2

(have conference with John before resetting dep mon.
Corner coned be 6.4' too far south 1962 CoHD.
" " 3.7' " " " 1935 CoHD.

10-12-72. Checked RPs. Power pole RPs OK hard to check
corner fence post dec as it 30' above road ±
found 1/2" pipe 1" below black top.
- ran & taped line north to 27-28-33-34 found 10-10-72
set BQ PoT on Cut-Out of old road on line 1/4 33-34 at 569.05
- found C1M at 1/4 33-34 at 2629.39.
- found C1M at 27-28-33-34 at 5255.28
Set PoT temp at 4023.08
Meas W line ~~10-18 2603.11~~ To ~~measure~~ set from CoHD line.

7-79 Corner 66' N & Co. Rd 9

R T. Fuller 2627.62
" 5255.24

(#733405) (3)

Section Corner South 33-34 Haverhill 107-13
North 3-4 Marion 106-13

6-27-1980 (1980 Remon. Bk) N 3-4 : Removed CIM set 1979 and also CIM beneath it.

7-2-1980 (1980 Remon Bk) 1/16 East : Dug from Connie's (accep) iron (in concrete) for 2' North, 2' East, 1½' West, and 1' South. Found a 3" diameter by 4" long piece of stake n very small post .7 North and .7 West of the iron. Found nothing further. Set iron with piece of concrete back at it location.

Geo W. Ls
80.00 Set post & mon. alum. stake to corner to Sections 3-4-33-34. Bk. to mon. & post found. Planted O.E. Dugs Orig't. M.E. Hyde Surv.

8-18-81 South 33-34: Set a CIM at double the line and measure from 5¼ Cor 34 (set 7-28-81) over stake found at the 1/16 West (7-2-80 fd). The corner is 4½' West of the ℄ Co. Rd. 11 & ±72' North of the ℄ Co. Rd 9 and 6.48 N and 4.58 W of FCHD
RP: C.S.D. in S. side transmission pole ESE 54.32
CH.Disc in pp SE 148.20
CSD in power pole SW 123.49
5/17/89 FD CIM IN GOOD COND. IN BLACKTOP

JUNE 1994 FD CIM NEAR SURFACE. USED REF PT EASTWOOD (CONC. MONUMENT) TOP BANK 2 P. POLES N. JCT 9 + 11 W SIDE RD.



– CONT →

SECTION CORNER SOUTH 33-34 HAUGHILL 107-13 (4)
NORTH 3-4 MARION 106-13

JUNE 1994 CONT. T @ EASTWOOD #733405
&RT TOP CENTER LIGHT TALLEST RADIO
TOWER E TO S. SEC COR 33-34
329° 55' 53" dh 05 121° 31' 08" dh 03
208° 56' 49" dh 05 0° 32' 05" dh 03
120° 59' 04" 120° 59' 03"

TO S. SEC. COR. 33-34
VA 93° 35' 15" dh 00
SLOPE 493.80 HOR. 492.83

11-14-94 CHD SET 1" SQ PIPE W/CAP.

Aug 1996 Dean Strange of People's Coop
Found 2" Disc in Road Surface.