X C.I.M. set by Co. Hwy Dept. #733505

section corner south 34-35 Haverhill. 107-13.
north 2-3 Marion 106-13.

6-1873 Hunter p228 no 231 & 35 Pat Lawler.
found stone center road as corner, stated stamp SEBT.
other tree gone. left stone as found.
- Mens east 39.88 to stone set as 1/4 35.
2632.08

Co Hwy Dept. (See field Bk 88 p.9 = Corner assumed in 12-1937 Sta. 186+02.7 Δ=0°02'
used corner many years.

Dec	top fence post	NE	52.69
"	" " "	NW	59.21
"	power pole	S	47.51
"	tele pole	NNW	56.24

4-3-73 found C/M down 2"± set by county Hwy Dept. who claims extensive research for corner tracks as far as late 1930's and no corner ever found.

County measure north to flat limestone standing by corner post Book 88 page 73 2626.5' then 2647.5' north to limestone believed not true corner found 8-1968 when RP's varied considerable making county stone 8'± westerly

Elect meas N to stone by corner just at ¼ 34-35 (2622.3

June, 1857 John B. Fellows Pg. 26 No. 42 used Sec. Corner. Meas East 39.57 chs. & South 39.90 chs.

Cor Notes

S[illegible] 2-3-34-35

B- 0-E 14 N 49° E 17

" " 12 N 52 ± W 15

" " 16 S 55 ± E 25

" " 6 S 55 ± W 25