1 8-16-73 dug center road. cones gone. set nothing
11-18-1974 set 1¼" x 8" Pipe flush with concrete
¼ corner: South ¼ 36 Haverhill 107-13 (1)
North ¼ 1 Marion 106-13.
#7336 Of

5-1892 Hunter P205 No 213 L36 2hos Lawler.
Corner missing, found stump of B.T. N Brennan.
with marks plain. reset corner with stone 3"x4"x8"
– Meas north 39.86 (2631.76) N55°E
– 16 west set short stake in center road M&L 19.98
N89°5'W.

1966 line from S ¼ 35 east. Act Rec County

1648.0 1643.4 | 989.4 989.4 | 1318.7 (1331.5) | 1318.7 1327.0 | comp. 2624.16 1310.8 1322.6

2632.8 2636.7 2638 | 2658.5 2637.4 2659.3 | 2633.4 2624.16 2636.2

Co. Hwy Dept. R P's to S. 1/4 cor. Sec 16 T 43 R

Spike in pine S E. 43.4

" " " S 60.4

S/P 265+36 ± P I. 0°4' Rt.

8-16-73 dug entire road with D 8 Dozer Freeman Construction - found clay close road Cut & gone dug 4' deep x 20' wide across entire road. old road washed or worn or graded away road to clean clay. found nothing set Nothing. Must try and find some evidence of 1/16 alone between Centy 36 and N 1/4 36 to prove Center then intersect range line as best as possible.

1/4 Corner South 1/4 36 Haverhill 107-13 (2)
North 1/4 1 Marion 106-13
#733604

Govt Notes
40.00 Set 1/4 Sec. Post
Burr oak, 10" N 32 1/2° W 541 lks.