11-18-1974 set 1¼" x 12" pipe flush with concrete
#733605 (1)

section corner south 35-36 Haverhill 107-13
North 1-2 Marion 106-13

5-1872 Hunter P205 no 213 L36 Thos Fowler.
J Fowler.
M Brennan.

Corner gone, no evidence of corner by extensive digging. Mr. Mulverhill owns fence south was built when corner stood and south road fence was set 2 rods south of corner. set stone 2 x 5 x 12". corner came in center road. North road fence also 2 rods from corner.
Mear with Notes A Hooksett 39.72 (2621.52
-16 east set short stake center road N & L 19.98.
to stone 3 x 4 x 8 reset from B tree stump, marks plain.

6-1873 Hunter P228 no 231 L35 Pat Fowler

-over-

found stone set P205
- west set stake for division of SE 1/4 35 as deed calls for 60 acres east - 100 acres west here shortage.
- west 14.98 (988.6' then 24.97 (1648.0'

corner now iron rod in B Top, origin McGhie no RPs.
- meas 1966 J Kerr. - west to fence north 989.4 R 988.7
then 1643.4 to S 1/4 35 R 1648.0
- meas east to fence north 1331.5 R 1318.7.
then 1327.0 to 1/4 line fence north R 1318.7.
- from S 1/4 fence east to 1/16 fence north 1310.8 } or 2633.4
then 1/16 fence north east to proven loc/p on 1322.6 } comp R 2624.16.
mile south line 36 actual 5291.9 comp R. 5261.56.

8-9-73 dug 10' square 8' deep in area of corner, roots unbelievably went clear to bottom, super hard, found not a pebble.

(2)

#733605