#740104

9-15-63 set C/M over iron, small ele fence post by corner in open fence line.

1/4 corner 1-12 Cascade 107-14

See field BK 15 p. 3-20

6-1900 Robt Fraser. P646 to 652 No 582 L 1-2-11-12.
Corner stake plowed out by farmer plowing too close to hedgerow. Mr Schaick was only pioneer who knew of its former location. after relocating corner this man fancied it came exactly as he would have located it
set new burr oak stake between 2 stones.,
4" burr oak N 3° W 47½ lks. (31.35'
-16 north set stake on. 70 lk offset west M&L 19.92½
which came in middle of river.
-16 east drone stake M&L 19.97.
-16 west " " " 19.94 3/8.

- over.

9-15-1963. JKerr.

Corner stones found and used in recent surveys.
set C/M onek iron rod in wide wooded fence row.
very little if any important fences.
- set 3/8" elec. fence steel post by corner.
- Nail in hub in 16" burr oak. NNE 6.5'
- No east-west fences or property boundaries.

Gov't Notes Cor. Knock 15 cy
40.00 Set stone 1/4 sect post
West on true line between sects. 1 & 12
40.00 Set 1/4 sect post V 8°41'
Bur Oak 9 N 68 W 133
Bur Oak 12 5 20 E 165

May, 1857 Thos. Hunter Pg. 24 No. 39 used 1/4 Cor.
11... North 19.72 chs. mfL-B.T.s (S 65 1/2° E 38 lks.) (S 23° W 77 1/2 lks)