X Stpipe set By Mc+B = 1972 by meas from So. over ¼ Cor

Aug. 7, 1979 Set C.I. Cap/pipe inplace of Mc+B pipe (removed)

¼ Corner 1-2 Cascade 107-14 (1)

fd BK 15 p. 3-20 #740106

6-1900 Robt. Fraser p646-652 No582 & 7-2-11-12

Quote- found old stake broken off. Mr Kaneski owns that it was the right stake and son of Mr Podolski also said the same. A white Hookstake put there by Hunter and these two parties were with him at the time. It fobbed with clearing running east and west. Witness trees grubbed and gone. The stake came by side of cattle pass. The stake stood 2 or 3 feet east of brush fence when it was put in place of old stake in pits and mound. New fences 2 or 3 feet further west of where brush fence stood. Tested corner by meas. given by Hunter from corner to ¼/6 corner north which were exactly the same, that is the line of fence at ¼/6 cor. which was set when stake was standing at 80 rods. From ¼/6 north to twsp line came about where Hunters said section corner stood. +50 links north from fence post. Concluded he was right - over

set bur oak stake sqared and properly marked
took boulder as witness S 26° E. 84 links (55.44 (red granite)
10" Soak N 34° W 32 " (21.12'
-16 south set stone & stake N & L 19.78 5/6. (1306.0
see below marked.

Sanstone - Kasseler found iron set by McGhie as corner.
Sanstone run line south 2615.24.
- also run line from 1-2-11-12 west to 1/4 2-11 and set iron (1/2")
373.37. west of 1-2-11-12 then 1977.09. North of 373.37.
To 1/2" run then 35.7' to E road

B trees to 1/16 south. 1900 - N 25° E 6" oak. 23 1/2 L - 15.51
N 59 1/2° W. 12" Elm. 36 L. (23.76'. 128 3/2 L (84.7'

± 1972 McGhie & Betts - set 5/8" pipe by Line & Meas.
over 1/16 Stone South.

6-1883 T.H. Field BK 14 p. 5-6
Shows Meas. N. 20.08 Then 19.39 To Sec. Cor

#740106 (2)

Cascade 1/4 corner 1-2
Geo'l Watts Mt. Hemlock 1857
40.00 Set temp. 1/4 sect. post
5.13 W on true line between sect. 1+12
39.30 Set 1/4 section post, in mound
with brush, pits, charred stake +
Osage Orange trees N. E + S. W.

May, 1857 Thos. Hunter Rg. 24 No. 39 Meas. East 39.82 chs to cen Sec.

Aug. 7, 1919 Co. Surveyor - dug for R. Fraser's wood Stake assuming that MC+B set ½" pipe set from South (S.E. Cor. 2 over 1/16 Cor. N.) was set correctly, did not find stake or any Trace of it except dark spot in soil down about 18" and about 0.4' Nwly of MC+B pipe. Accepted MC+B pipe as correct location as it checked within 0.5' of the Tie To

the boulder S 26°E 84 lks (55.44') taken by R. Fraser. Checked Brg with Transit Compass and found it close (about a foot) Boulder is a red granite about 3' dia. and the westerly one of Two.

Set a C.I. Cap in 1½" sq. pipe about 30" long over a RR spikee and stones and glass set about 2' deep under N-S Fence (nearly.) Removed McHB pipe. R.P.'s MD/DOT Copper disc in 6" Elm. West 5.83' and " " " in 6" Elm South-Toe and about 59' EAST of ℄ Crushed Rock road.

4-19-79 Found McHbr pipe and cap in the N-S fence on the E side Co. Rd. 137 (1979 Reman. Book P. 31, 41

5-15-79 1/16th Note: Took shots in the 1/16th fence (East) Note of 1/4 Cor 1-2 to determine line of fence

1/4 CORNER 1, 2 CASCADE 107-14 (3)

7/27/92 Took references for road construction

R @ Ref pipe/cap on top of east back slope CR #133 #740106

RT West lightning rod on Kavaleski barn roof north to 1/4 cor 1-2

AVE ∠ 294° 25' 00"

To 1/4 1,2 (calc/pz)

VA 95 10 33 dvor

SD 161.19 HD 160.53

8-21-95 – SET 1" SQ PIPE W/CAP IN ROCK DUG INTO BACK SLOPE OF CR #133 NEW GRADE AT REF LOCATION FROM BEFORE GRADING. THE CORNER FALLS 49½' WEST OF ℄ CR #133 ON CURVE.

CSD IN PF # 53495 S 75° E 101.92