1 8-9-1966 set CIM. in place of center huge stone set by J Kerr. 11-1916 - stone now just south of corner. 3-29-73 set ½" iron down 12" at true corner did not find CIM. 11-10-77 SET CIM over rod #740305 (1)

section corner 3-4-9-10 Cascade. 10 7-14

4-1870 R Perry. P108 no 147. Sec 9 & 10 M Clark.

found a new stake in mound with pits plain.

-16 E set marked stake M&L 20.10 1326.6

-16 S set stone M&L 1300.2 to stone set 2600.4 M&L

5-1911 C Larson. P166 B. Parts of Secs 9 and 10. J. Clasen.

Outside "found stone"

Meas west either meas or copied 40.12. 2647.92.

Meas east very likely copied 40.20 2653.2

Meas east same as Perry (should check entire mile above)

(over)

11-1916 J Kerr. B 252 B Lee 3 (S½) 10 J Bandel & others.
found no corner
- ran and meas line from ¼ 9-10 (not described) north
to section corner N-3-4 on township line which had to
be re-set midway and on line from N¼ 4. ~~(not described)~~ shows stone on plat and mentions stone in descrip
and N¼ 3 (stone) at 2639.5' where stone was set.
- meas 4 1½ miles 7759.0'
- set point on direct line at 2600' from ¼ 9-10 as temp cor
- checked meas from east 2631.4 and also record 4
2653.2 on same line set stone in place 4 stake on
random line. "Quote- The stone as set corresponding with
all old landmarks & fences and according to the statement
of settlers who had seen the old corner. It was approx.
on the same place.
Lee Card (2)

Card # 2. 3-4-9-10 Cascade. 107-14. (2)

B 252 B. J Kerr Cont. 11-1916. #740305

set stone east at 1315.7 M & L.

(Cannot find any desc. or proof (except "stone" marked on plat) that anything ever set at 1/16 " or 1300 stake location" where perrys stone should have been located if notes were at hand of that survey between 1/4 9-10 and Cor set. Nothing leads to setting corner at 2631.7.

Perry has west line 10 straight and N-S 1/4 line straight.
L side W 1/2 10 2642.0 — Center west to 1/4 corner. 2648. N side 2653.2

J Kerr has N-S 1/4 line not straight but center set M & L. 2642.25 E-W
L side 2639.0 Center west. 2642.5 N side W 1/2 10 2631.4

Check for 1/16 north of 1/4 9-10 and corner north of river and check enters perry line. (over)

2-1960 J Kerr B78 P44 & 3 dr Lufgren.
used stone corner as set 11-1916.
- re-run line east to correct ¼ 3-10. still had 2631.4
- set iron rod (no mention of stone 1916) ground likely frozen hard.
Midway & line 1315.7. as in 11-1916.
- ran from corner north again to N 3-4 (believe.
this was time dug with torch 5' deep at N 3-4 in Co
road using only RP left. the hole in rock ledge-found
stone and put riser over it. Meas now 5154
5159 in 1916. set 1/16 iron north at 1296.61 using
proportions of 1296.61 - 1296.61 - 1296.61 - 1264.18
also set 1/16 iron in Center SW ¼ sec 3 M&L. 1316.24 on.
E-W 1/16 line (don't know if above 1/16 line blazed to 1/16 iron south.
See Card 3

#740305

Card # 3. 3-4-9-10 Cascade 107-14 (3)

8-1966 found huge boulder. 6" X 24" X 30" very hard. dug huge hole south and tipped stone into hole and set C/M. where center stone as near as possible could be fixed - set C/M with small boulders on E and W sides of C/M.

1.9' NNW to point on heavy angle steel corner post as follows



27.54. N 33° E to nail in hub on W side blazed pin oak which is most NE ly. of clump of 3 oaks, which are all suckers of large oak stump (no sizes)

(over

after setting C/M meas south to help find stone set at 1/4 9-10. (No knowledge of 1/16 stone). set 1300' N&L - found good 1/16 fence running west (farm boundry fence) at 1297.0 - Coin and found positive limestone in clear soil near 3' deep. (land slopes quite sharply up to W) and could easily have that much fill. Ines 1870 stone but as Hunter in 6-1870 Coned not find stone and took corner post raises doubts of entire line.

1/16 stone found south 1299.9 12-28-1972 Coned be Perry or set by unknown party when 1/4 9-10 set or Hunter did not find Perry 1/4 9-10.

best way to prove line between 9-10. search for 1/16 N of 1/4 9-10 meas & take line carefully. - also meas 1/4 3-10 1 mile west to C/M on brush fence corner. at N 1/4 9. believe Perry did best work & all noted.

Card No 4. 3-4-9-10 Cascade 107-14. (4)
#740305
3-22-73. Cont line north. set up on 125' ⑤ west
12-28-72 from CIM at 1/4 9-10 and alum limestone
found. 1299.9. south of 1/4 9-10.
PoT S found in place - note PoT 1/4 9-10 1.1' N of 90° to 1/4 9-10.
- found boulder vertical 5"x8"x16"± just west of corner post
at 1/16 north - at 1966 mens wonned be 1297. N to CIM.
and. 1298.2 S to CIM. but 135' east of 125' ⑤ line
- dug and found limestone in clear soil down 6"± slightly
leaning east definately stone set by Berry in 1870. and
exactly 10' west of J Kerr stone and. 2.3' north making
1300.5 S 1294.7 N. to J Kerr CIM.
Cont 125' line and set nail east 125' and 5.8 north
of CIM which fell nearly 21'+ west of CIM. over.

ran line from 1/4 3-10 west - meas on line to center (9/16 cor)
Created new corner post 1315.7 and considered 1 Ker iron
replaced by post - found 3" □ x 16" positive limestone
corner very vertical about 10' west and 2'± north of post.
- set 50' ⑤ at 1/4 3-10 and newly found stone and meas
west on offset line. corrected. 1325.12 and set nail
which fell 1.3 E and 1.1 N of nail from south. as
1/4 9-10 and 2 1/16 stones line up may set 3-4-9-10 on
line from south rather than east. RPS to nail.
bolt on angle iron corner post brace ESE. 21.22 19.23
nail from S - from E.

Nail in small cherry tree NNW 12.2 11.75
3-29-73 set final 1/2" iron down 12" for 3-4-9-10 after
re-run of line & elec. meas from south. moved 1/16 S .25' north.
21.0 direct to C IM E.S.E. 12.62 NNW to nail.
20.02 ESE to ⊥ post up 1' C IM 20.30 E - 4.30 S

#740305 (5)

Section Corner 3-4-9-10 Cascade 107-14

11-10-77 Removed Kerr's CIM and reset it over ½" rod set in 1973. Corner 20' W of N-S fence, 3½' N of fence E, and 9' So of fence W. Corner 20.30 W and 4.30 N. of Kerr's location

RP's: Spike in E side 5" Cherry NNW 12.66

Sp. & CSD in S. side most southerly 8" twin blazed Black Oak NE 37.96

NW corner of iron corner post (at top) ESE 20.18

"Govt mons" on Karick 55y 80.00 Set post in mound with trench. Bdy chopped strike, 4 orange. Orange small 0 2 each angle for corner to section 3-4-9-10

5-4-79 Set Survey Marker Sign and Post 1' NE

4/4/90 FD CIM 1 1/4 SIGN 1/4 POST IN GOOD COND.