#740404 (1)

5-19-1961 set C/M on fence intersection.

1/4 corner 4-9 Cascade. 107-14

4-1870 R Perry P108 no 147 & 9-10 M Clark.
fence corner claimed by oldest settlers to have
been placed in orig mound. - accepted as correct.
-16 south set stone M & L. 19.78 (1305.5'

5-1911 C Larson P166B parts sec 9 and 10 J Clasen.
used corner post as corner as recorded. this calling
of corner proves that survey as platted on film is as follows
North line diagram is section line with "2" as 1/4 4-9
"1" as 3-4-9-10
- meas east "2" to "1" 40.12 2647.92

(over)

5-1961 J Kerr B 82 P60 NW 1/4 9. August Steve.
accepted badly rotted corner post in plum bag as corner,
clear field (common land, no fence north). set C/M in
place of rotted out corner post. set prop rods on 1/4 line
south. which come well east of concrete matt of old highway

9-1962 J Kerr B86 P 7. NW 1/4 9 August Steve
run N side NW 1/4 9. dug deep for NW cor 9.
- set prop rods in road 1222.2 from NW 9 - then 389.82 east
to RW triangle next to freeway. No apparent total mess of line
C/M has no definate RPs only that it lies in brush
area in line old fence E-W S.

Cascade .25 corner 4-7 #740404 12
Gov't Notes M. Kavanagh 1854
40.00 Set temp 1/4 section post
West on true line between sects.
40.00 Set 1/4 section post in N 49 W 8.45
mound with trench, pits, charcoal
stake, Osage Orange trees N.E. + S.W.
4/4/90 FD QIM ON EAST SIDE OF CORNER POST
NAILED SURVEY SIGN ON WEST SIDE OF POST