/ 6-2-72 set 1/2" rod from line & meas from east. (1)
4-7-1975 set C.I.M. over 5/8-28 rod M&L at 2636.66
#740706

1/4 corner	west 1/4 7	Cascade	107-14.
	east 1/4 12	Kalmar	107-15

6-1870 Perry P122 No 157 & 12 C Grassley.
set stone 4 1/2 x 7 x 24 M&L. 39.95. 2636.7
-1/16 north set stone 4 x 8 x 16 M&L 19.97 1/2. 1318.35
-1/16 south set stone 4 x 5 x 22 & stake M&L. 19.97 1/2. 1318.35
also set stone 4 x 8 x 20 9.98 3/4 north & above 1/16 cor. 659.18
-1/16 center NE 1/4 12. set stone 2 1/2 x 8 x 20
-1/16 center SE 1/4 12 set stone 5 x 5 x 15 & stake
also set stone 3 x 5 1/2 x 15 north above 1/16 cor line E.

5-1876 Hunter P295 No 290 & 7 Grimm, Hoffman
found stone center road. P122. Ripley, Martin, Grassley (surv)

-1/16 north found stone P 122 to be 2 links too far south, removed set stone 2 x 5 x 30 true N & L 19.97 1/2.
-1/16 east set stone 3 x 7 x 18 at 18.04 then 19.81 to center West line 7 and N S 1/4 line 7 recorded straight.
recorded N line (W 1/2) 38.35 — S line (W 1/2) 38.10 making a mean recorded mean of W 1/2 & E-W 1/4 line as 38.27 1/2 it being short 37 1/2 lks or 37.85 set stone accordingly.
-1/16 center NE 1/4 7 set stone 3 x 5 x 22. direct intersection.

present day terrain - favorable. tops of road level with fields. Slight slope 200' North.
11-11-71. Co surv. set nail on line from stone found at center 7 over stone found at 1/16 W. at 1307.9 corrected for temp 1308.3 ach 30°. R, 130746. and see Card # 2

Card # 2. W 1/4 7 Cascade 107-14. (2)
E 1/4 12 Kalmar 107-15 #740706

11-11-17 Cont — cont west from 1/6 stone 1190.64 a record
wood line 15.95 offset north. set nail by transit on the line
line RPs. 71.61 SSE To orange cap on S side PP 2459.
~~46.01 SW To root Beer cap on SE side stob pole~~ - gone

12-3-71. Meas from nail at intersection crossroads at
W 7-18 E 12-13 north see W-7-18 card.
found nail to be at 2635.6 R 2636.7
Cont meas north to nail at W-6-7 E 1-12 found to be at
2640.0 using W 1/4 7 nail as .00 R 2636.7.
1/6 fence west N & W 1/4 7 Corner at 1317.0 indicating nail at
W 6-7 too far north and too far east.

6-2-72 Co. surv. found nail set 11-71, lucky as tele pole SW gone entirely. dug entire area with tractor, road gone to clay ledge boulders in fill - replaced nail with ½" iron as found. which is 1190.64 W of 1/16 stone - a record -

12-3-71 corn picked meas Center 7 to 1/16 west 1307.46. R1308.3

- will search for 1/16 north of W¼7, if found will check meas and alignment of rod. set. may go slightly east ?

RP 6-2-72 71.58 SSE on slope to orange cap SW side PP # 24059.

33.85 4"± N of W to S edge steel post of telesign

49.53 W to cone nail in south side 4" cedar post

See Card # 3 for 1/16 corner N & S of W¼7.

Card # 3 West 1/4 T. East 1/4 12. #740706 (3)

Cascade 107-14 Kalmar 107-15

1/16 corner north of above. Corner found 3' deep
found 2"x5" top of 2x5x30 L stone as reset 5-1876 by
Hunter, finding R Perry stone 4x8x16 to be 2 lks too far south
- broke glass on corner and set 1/2"x2' rod reset as corner
- corner .65 N of 1317 nail set from present W 1/4 T. Drill Zap.
52.87 SE to staple on ground wire at level up near 4' ±.
on power pole 24052.
33.65 W to small punched cross in 2" steel pipe
by corner post leaning west

over 1/16 South

1/16 south of W 1/4 7 Cascade E 1/4 12 Kalmar.

found 4"x5" top L stone 4' deep in near center road.

- Poke glass on stone - set 1/2" x 2' rod riser at surface.

- Corner came .07' S of 1317 nail from 00 random at W 7-18 Cascade E 12-13 Kalmar Zap later

44.8 SE to orange cap on SW side PS 24068.

59.25 NNW to chiseled cross in center W headwall mes 3' tele

59.0 NW to S edge steel tele cable warning sign post.

#740706 (4)

W. 1/4 cor Sec 7 CASCADE 107-14

E. 1/4 cor Sec 12 Kalmar 107-15

4-7-1975

Reran + meas. the sec line & set a C.I.M. over a 5/8"x8" iron rod M.L at 2636.06.

R.P.'s

Bottle cap on S.W. side PP # 24059 S.E. 71.18

C.S disc on S. side cor. post (for fo line West) W. 34.50

Corner falls in line with fences E.+W. + 1'± West of ℄ of Twp. road.

71.23
34.60

1/16 South. 4-7-75

Set a 1¼" pipe as the cor. flush w/ Bit. surface

- took No additional R.P.'s

1/16 N. of 1/4 cor.
Set a 5/8" x 14" iron rod in Bit. surface
exactly in L at 1318.03 which only moved
it a couple hundredths from the point
used in 1972.

R.P.'s

C.S. disc on S.W. side pp# 24052 S.E. 52.81
Center Bottom 2" pipe post W. 33.74
corner falls 2' west ℄ of Twp. road + in line
with fence West.

Gout Notes

40.00 Set post + drive channel stake for
quarter section corner. Build mound + mark.
planted S.E. Osage Orange, + N.E.
Apple trees.