#740806 (1)

6-19-1964 set CIM over 1½x14" pipe.
11/22/69 SET 10" CIM OVER CIM

1/4 Corner T-8 Cascade 107-14

5-1876 Hunter P295 no 290 L 7 5 parties

Corner gone, no evidence or knowledge

set stone 2 x 4/12 x 23 M & L 40.19 (2652.54'

-16 north set stone 2x5x15 M & L 20.09½ (132627'

-16 south set stone 4x 4/10 x22 " " ("

-16 west set stone 1½ x 9 x 18 M & L 19.92 (1314.72'

-16 center NE 1/4 sec 7. set stone inters lines.

-16 center SE 1/4 L 7 " " 1½x6x15 intersLines.

Can't find any record when stone found and pipe placed by stone with glass etc L B25 P37-1941.
Case Lwp road survey. Found stones and iron rod.
265.3 south to L W cor 8.

(over)

6-19-64 J Kerr found iron and stones & glass.
set CIM over 1½ x 14" pipe etc.
Corner lies in line of fence running east.
" " 2' west center traveled road.
Disc power pole. SSE 144.7.
" " " NNE 114.2
¾" x 28" pipe up 9" in fence line east 100.0'

1938' Co H&D B103 P51. found flat limestone.
Disc in Cor FP E 20.4 - Disc TP SW 68.5
Meas north 1326 to ⅛ found then 1325.0
-16 North came in line fence west & road south.
Could be in curve area

11-8-77 Found CIM leaning East. Dug down to pipe and reset CIM over it. Pipe was .2 N and .5 W of leaning CIM location. SET SIGN & POST ~~[illegible]~~ IN FENCE LINE WEST

Cascade 1/4 corner 7-8 #740806 (2)
Govt Notes M. Kanouse 1854
40.00 Set 1/4 sect post - no wit + - ch
Pits, chained strike. + Osage Orange
Sets WE + SW

July, 1857 John B. Fellows Pg. 26 No. 41 used 1/4 Cor.
Meas. South 40.20 chs. - Meas. East 40.05 chs.
1/16 North 20.00 chs.

May, 1867 H.E. Horton Pg. 84 No. 129 Shows 1/4 Cor.
used to break down West half Sec. 8
Meas. South 40.06 chs., 1/16 East 19.92½ chs. to Cen Sec.
1/16 North 20.03½ chs. m&L

11/20/89' DUG WITH JACKHAMMER IN BLACKTOP
FD SPIKE, FD CIM DOWN 14"
11/22/89 SET 10" CIM OVER CIM
Rp's
114.14' NNE TO CHD DISC. IN PP # 36445
143.20' SSE TO CSD IN PP # 46315
SET SIGN & POST 30.5' WEST