#740905 (1)

9-5-1963 ✓ set C/M over pipe already in place.

section corner. 8-9-16-17 Cascade. 107-14

4-1870 ✓ R Berry P108 no 147 L9&10 M Clark.

found old corner. claimed by C Babcock as true corner.

set stone 3 x 4 x 19"

- Mens east 40.00 then 40.00 to SE 9

6-1892 ✓ T. Fraser P 489 no 464. L17&20. F Yoman. T Crawford.

found stone set. P108.

- west set stake at 18.68½ 1233.2. then.

- set stone ¼ at 21.17½. 1397.5 total 2630.7

39.851

39.86

(OVER)

Corner as pipe in ℄ east-west road many years.
9-1963 replaced pipe with C/M. drove pipe down.

Center 36" maple. NW 45.7.
" " SW 43.7.
spud. power pole. SE 35.48.
fence line running south E 4.5
line center east-west road.

5-1956 J Kerr B63 P12. L.L. Rossi
Meas south line ℒ S 5259.7. set 1/16 cor at 1314.93 from
SE S. - RP 1/16. ℒ TP SW 10.4 - ℒ PP SE 48.4
property starts 254 W of 1/16 N 590.64 W 336.0

B25 P37 found corner 1" pipe.
1-2-73 Zap SW 9 to SE 10. Meas SW 9 to S 49. 2634.29.

#740905 (2)

Section Corner 8-9-16-17 Cascade 107-14

7-1935 C.H.D. - found stone monument with old rotted stake on east side of stone 4 ft. deep - set 1" pipe on top

Govt Notes ✓ M Kanick 1854

80.00 set ¾ post for corner to sect 8-9-16-17
Erected mound with trench, pits, charred stake & Orange Orang scrolls at each angle

---

July, 1857 ✓ John B. Fellows Pg. 26 No. 41 used Sec. Cor 1/16 west 19.98 Chs. M ¼ L

July, 1857 ✓ John B. Fellows Pg. 27 No. 43 used sec. Cor Prop line west 14.98 Chs. then 24.98 Chs. to ¼ Cor

4-4-84 ✓, Sec Cor 8-9-16-17: Set a 5/8" re-rod over the CIM and up to the road surface and packed in Blacktop.

6/18/92 County Surveyor Set ref rod 5/8" x 25" rerod Rp's 10' south of face of 50" maple & driveway west 13'

To ref rod & Rt Assisi Hts bell tower with cross on top to sec cor 8,9,16,17 5/8" rod
& Rt 32° 55' 34.5"

To sec cor.
VA 92° 26' 06"
SD 69.89 HD 69.825

Rp's to sec cor.
Edge of manhole ring at chisel mark NW 48.87'
Top center fire hyd. ENE 110.01'

"740905" E 1-28-99

SEC COR 8-9-16-17 107-14 CASCADE LTA BB JPJ

FOUND 5/8" REBAR DOWN 0.3' IN GOOD CONDITION

CORNER FALLS IN ℄ DEAD END 55TH ST NW

17' ± EAST OF ℄ DRIVEWAY NORTH. REF ROD

SEEMS TO BE INTACT. THOUGH 50" MAPLE HAS

BEEN CUT DOWN. STUMP STILL THERE.