9-14-1963 set C/M. over 3/4" pipe found, a stone, a large quary stone set by J Kerr. 11-1916, claimed some distance below pipe and carefully maintained #741004
Removed 8-21-69 for grading - RP$ only & pipe dup.

1/4 corner. 10-15 Cascade. 107-14.
4-1870 R Perry. P108 No 147. L9&10 M Clark.
"found this point as 1/4 Cor. but did not retain it."
Meas east 40.03 (2642 to stone set as section corner).
Meas west 40.03 (2642 to " " " " "
both by testimony of oldest settlers - no mention that
Corner was anywhere near on line.

See T. Hunter Book 5 p.41 Sec. 10 - Feb. 7, 1878
Fd Stake with Stone by Side Meas. E. 20.05 - 20.05
Meas. N. 19.70 = 1300.2 (over

6-1874 Hunter P256 No 256 S10 Philo Boardman.
Corner completely gone. replaced corner with small stake
driven even with surface in middle road midway between fences.
by a line from S¼15 over stone at center 15 set in survey
4-1861 when all ¼ posts were standing, this line
intersecting direct S line of Sec 10. Meas long way from midway
as in P 108 (east 40.10=(2646.6) west 39.67 (2618.22
Perry 2642.0 midway no line mentioned. 5284.0 2646.6
Meas north 39.44 (2603.04' 5264.82

5-1911 Chas Larson B166 B W½9 E½10.
No mention or dist S ¼10-15 but showed meas to S W10
as 40 chains a typical Larson likely deduct use corner.

11-1916 J Kerr P252B. Secs 3-10 J Bandel & others
Meas south from N¼10 to S¼10 5219.0 See Card 2.

Card # 2 1/4 10-15 Cascade. 107-14 (2)

11-14-1916 J Kerr P255 ran east from SW cor 10. total mile 5278.0. set large quartz rock with + at 3958.5 - came at 1/4 10-15 2639.0 #741004 set 3" iron pipe at 1319.5. all on direct line. no desc. of SE corner 10 anywhere in survey. - finally set center 10. midway on both 1/4 lines N-S 2609.5 E-W 2642.25.

1967 J Kerr. B93 P.13. NE 1/4 10 Lyle Dualey. ran & meas. S line of SE 1/4 10 2635.35. and set 1/16 iron at 1317.67. which fell 22' E of fence N. also ran N-S 1/16 line of SE 1/4 10 2601.15 - set prop corner. 550' S of 1/16 pipe which has N & L. 1316.07 betw Center 10 & E 1/4 rerun this survey.

ran N-S 1/4 line 10 direct so center 10 set at true
inters lines - meas from. N 1/4 10 to new center. 2615.3.
Not. 2609.5 as in 1916 survey. east from Center 26.32.14
No meas center west or south this survey.
plot laid out in this survey adjacent to Trappers Hill plat
with east line as 1/16 corner and iron 550' south. and north
line of plot 1/16 corner and iron 550' west. - South west corner of
plat 519' south and 560' east. see P13B93.

---

summary actual proof & preservation of original J Kerr
stone set in 1916 survey.
1935 Co HD. old stake in center pile of rocks. set 1"x2"x16" stake on top of old stake
No proof that pipe in place used to place C/M over stone.
Elec meas & line from 1/4 9-16 east. See Card 3.

8-21-69. removed C/M open pipe set 1/2" rod in its place.
set 1/2" rod. 200' east on 1/4 line level road surface
RP to rod then 5'E 21.75 S of Sedge 66 boy. 131.8 ESE to PI# 33806.
12-1972 # 40538

#741004 (3)

Card #2. 1/4 corner 10-15 Cascade 107-14
B337 Co H D 1968 found. CIM Sta 52+58.62
mean south 26 27.2 mean north 2598.73
~~Sp D RP SW 93.28~~ - ~~Sp D RP~~ SE Gobbet
corner is P.I. 0° 34' left going north.

12-28-1972. Corner deep or gone in new black top road.
all RPs gone but SE PP and that may have been moved # now 33807.
-16 each in place. additional RPs.
43.0 NW to 7 up cap. on SW side creo Corner post
60.2 SW to long conc nail in top of 4" wood line brace post

over.

Transit RP to 1/4 10-15 buried in new road area.

RP Pole # 33806. ESE 131.8 now # 40538, telcne moved due south at least to a new pole from scratch. Tele box 5' west and 21.75 north gone. now 7' high wood sign post.

C & D Grading hub RPs to work out after C/M removed.

LW 84.24 LE 98.69

6-26-1970 C & D 72.75 72.84 LE to Lp PP # 33807.
49.15 49.08 NE to Lp PP #. 39620
54.25 54.15 NW to Lp PP #. 41071

3/4" rod placed in sub-grade likely.

1-2-73. Elec meas from. SE 10 to SW 9. cascade.

See Card (2) 9-10-15-16 2631.80 ~~2631.99~~ ~~2635.80~~ ~~2635.67~~

(SE 10) 2635.32 (S 1/4 10) (S 9-10) (S 1/4 9) 2634.29 (SW 9)

analysis of corner location indicates that T. Hunter's 1874 is farther West 10'± 5/8" rod R.B. Feb. 1976

Cascade 1/4 corner 10-15 #741004 14

Govt Mons Mon. Knoll 1954

40.00 set temp 1/4 scab. post

West on true line between scabs. 10-15

40.00 set 1/4 section post in ground 0.8' 45° with trench, piles, charred stake & Osage Orange reset W. 1/4 S.W.

± 1/16 Corner - 8-22-1985 RWB - found 2" pipe - Took Ties.
See Card #4 on Sec. Cor. 9-10-15-16

11-19-96 - FOUND PIPE W/ PLASTIC CAP 6" DEEP IN BLACKTOP CR # 112. 12' NORTH OF ℄ 55TH ST NW RUNNING WEST + ± 15' NORTH OF ℄ 55TH ST NW RUNNING EAST AT INTERSECTION

(9)

4-13-99
JPJ BB

"741004"

FD 5/8" PIPE IN GOOD CONDITION.

AT@ TRAV PT #24 (CITY PT)
ART #13 TO "741004"

240 48 46 dh01 — 243 11 20 dh02 — 245° 25' 50" dh02
0 03 54 dh04 — 02 26 22 dh02 — 04° 40' 53" dh02
240° 44' 52" — 240° 44' 58" — 240° 44' 57"

TO #13 (5/8" PIPE/CAP DOWN 1')
VA 90° 22' 23" dv 01
SLOPE 817.395 HOR 817.375

TO "741004"
VA 90° 29' 12" dv 03
SLOPE 143.145 HOR 143.145

AT@ #13
ART TRAV PT #24 TO 1/16 E OF 1/4 10-15
173° 17' 25" dh01 — 175° 36' 42" dh01
0° 06' 41" dh05 — 02° 26' 00" dh05
173° 10' 44" — 173° 10' 42"

TO TRAV PT #24 (120d SPIKE)
VA 89° 40' 44" dv02
SLOPE 817.415 HOR 817.40

49.1440

"741004" 1/4 COR
SURVEY CREW SET PK
BLACK TOP 18TH AVE NW
TIE OUT TAKEN IN

10-15 CASCADE
NAIL AT SURFACE OF
+ 55TH ST NW FROM
APRIL.

11-12-99
EPA BTB RF

1/16 E OF 1/4 COR
SURVEY CREW SET
OF 55TH ST NW
APRIL.

10-15 CASCADE 107-14
120d SPIKE IN MEDIAN
FROM TIE OUT MADE IN

11-12-99
EPA BTB RF