5-1461 Cem set later destroyed, now sewer manhole.
#741504 (1)

1/4 Corner 15-22 Cascade 10 7-14.
5-1870 R Perry P 178 no 189 NE 1/4 S 22 Boardman Evans.
Corner gone - reset 30' from point in Boardmans
fence he agrees correct. fence south.
-16 south stake N & L 20.09½ - east N & L 19.99.

5-1912 D Williams P 210 B NE 1/4 22 Blanchard. Hagerman.
found boulder stone with old stake beside it.
-16 east set limestone N & L 1319.0'
-16 south set limestone N & L 1326.62.

Note: See T. Hunter BK 5 p. 102 Sec. 22

(over

1941 JKerr B 24 P 77 L 22 Sam Allen.
found boulder recorded.
± meas west 2641.5

11-1961 JKerr B 83 P 17. NE 1/4 22 Ted Arnett
run line N 1/4 to NE 1/4 22 2638.44. (corner grey boulder
-16 south meas to 1324.77
above 1/16 east meas 2638.5
± RPs to corner when set as CIM now gone B337. 1969
steel angle fence corner NE 46.23. Hydrant - cross on NE bolt
Sp pipe pole NW 37.65 SW 43.03
Sp guy " " SW 40.82 meas N 2631.4.

B 340 Co Rd. 1968. RPs to 1/16 corner south. new 22.
iron pipe in place in ℄ 18 ave. meas east on 1/16 line 2638.24
Sp st. light pole NW. 46.59. - Sp D in PP SSW. 123.98

Cascade 1/4 corner 15-22 #741504 (2)
Gov't Woks Mt Karrick 185°
40.00 set temp 1/4 section post
West on true line between secs 15-22
40.00 Set 1/4 steel post in mound 80°53'
With trench pits, chained stakes,
2 Osage Orange scribed N.E. & S.W.

6-2-1981 Co. Surv. - found chis. Knotches on Manhole ring, made intersect and used the point to meas. south To check location of 1/16 cor pipe in ℄ 18th Ave and 37th St. N.W.
Checked Tie to Hyd. (Southwest) which chd 42.93 instead of 43.03, but hyd. is not same hyd. as Tie, being that we could not find cross on Bolt. other ties now gone.

6/18/92 County Surveyor set straddle nail after construction of road. ← @ 18th ; 43rd ∠ RT 3810

To straddle nail 0° 26' 43"

To straddle nail

VA 89 25 46

SL 1148 34 HD 1148.28

Previous distance 1149.40
move 1.12'

11/24/93 In 1992 we laid out the corner location from Traverse Ties & set Straddles we fd marks on M.H. Ring that were no longer good also "+" on cover. We destroyed the marks that we couldn't use & '+' on Cover. Then put marks on Ring for Intersect of final Corner.

#741504 (3)

1/4 CORNER 15-22 CASCADE 107-14

11-12-97 - WE VERIFIED THAT THE CHISEL MARKS ON RING WERE THERE AND CORRECT. WE CHISELED DEEPER.