1 9-5-1963 set C/M. over 3/4 x 12" pipe & brick well down below plow - Corner 157.0 East of fence FP SE 21.3 FP SW 20.7 (1)
(E'ly to of Gd R/W of E'ly RR

section corner 16-17-20-21 Cascade 10 7-14 #741605
6-1892. 2 hors Frazer P 489 No 464 Sec 17-20.
for F. Yoman J. Crawford Town Board.
Corner "F" Quote "there had been a corner post kept for the corner which had been properly marked, which post had been pulled up some years before by Mr Morrison as it came in the center of his farm. but on measuring from the 1/4 corner 17-20 east over the 1/16 corners found (stake buried by corner post). (1/4 17-20 west from west). we found the place where the old post stood which agreed with where Mr Morrison's side of it. the 2 mens agreed within a half link

and exactly on line but there was an angle at the
1/4 post - 16 west. found stake set 30 years previously
now M & L 19.61 1/2. 1294.59. East of 1/16.
1961 1/4 1294.425 West of 1/16

-16 S. set stone 5 x 10 x 18 M & L 19.90 1313.4

1936 Co H D. B 89 P 75. H Kalb.
found old post hole full of small bits of limestone as described
by Chas. Frazer. set 1" drill steel in center hole with bottom around it.

5-1956 J Kerr B 63 P 11 drill steel packed in rock 12" deep.
157' E of fence. along old right of way easterly of 2 RR tracks.

6-10-1960 J Kerr B 81 P 32. found arrow bar south, found
recorded h stone at 1314.9 Railway bt. 5' west of true line.
Its stone found at by. 20-21.
Leonard H 2.

Card # 2. 16-17-20-21 Cascade 107-14 #741605 (2)

Meas E. To 1/4 corner. 2618.2.

Land line south 1 mile and found 20-21-28-29. ore wood stake and 1/16 stone North of above.

In survey 5-1956 B 63 P 11. Ran west from 16-17-20-21 and set this at record 1294.59. for road survey for township corner iron could not be found in 1969. No land accurately fences running west where property line of Badger farms were found to be 27'± too far west.

9-5-1963. set C I N corner 3/4" x 12" pipe with buck and limestone piece well down below plow.

Me + B 1973± Elec. Comp. Meas. West To 1/4 cor. CIN = 2590.68

Govt works M. Barrack 1857

80.00 Set post for corner to sect.
16-17-20-21 in mound with trench
pits, charred stake & Orange
stones at each angle

July, 1857 John B. Fellows Pg. 27 No. 43 used Sec. Cor.
1/16 West 19.69 chs. m & L to 1/4 Cor

July, 1857 T. Hunter Pg. 36 No. 57 Shows Sec. Cor
1/16 West 19.69 chs. to 1/4 Post.

June, 1863 P.C. Compton Pg. 74 No. 108 shows Sec. Cor.
used to set 1/4 Cor 20-21 M & L, 1/16 East set-no meas.
Geo survey for breakdown N.W 1/4 & S.W 1/4 Sec. 21

June, 1863 P.C. Compton Pg. 75 No. 109 used Sec. Corner to
Subdivide N.E 1/4 Sec. 20

#741605 (3)

Section Corner 16-17-20-21, Cascade, 107-14

1-26-84, Sec. Cn. 16-17-20-21: Found CIM as described well down in cultivated field. Corner appears 157' East of most E'ly fence of E'ly (of two) railroad beds and in co± North of eyeball of power line ½ mile East.

5-21-97 - FOUND CIM IN GOOD CONDITION AT EDGE OF CULTIVATED FIELD DOWN 1.9', 43½' E OF 7" BOX ELDER. SET SIGN + POST 2' SOUTH.