9-5-1963 set CIM over rod #741606 (1)

1/4 corner 16-17 Cascade 107-14.

6-1892 Chas Fraser P 489 No 464 & 17420 F Yorranc. J Crawford. Town Board

set iron stake on N-S section line as intersected by actual fence line E-W which which was "struck off" by an early surveyor. No N-S meas.

-16 west set point M & L 19.80 ft. (1307.3

Corner found used in surveys CIM set 9-1963.

1959 J Kerr B 79 P 36 & 16 Lehmann Bros.

± meas N-S line betw 16-17 5229.85

- south 2630.06 north 2599.79

B 63 P 11 J Kerr. Meas west for road 1304.76

(over)

1969.

Run ~~[illegible]~~ line from Center 17 east to E ¼ 17. Had offset Nat W ¼ 41.67N marked E ¼ 43.15. set center on line and set rod in area of ⅛ corner for line only.

3' east of west edge of road.

23 east to east end road culv.

33' to nail in corner post east. very nearly on line.

fence west ~~south~~ of line.

– C/M at ¼ 16-17 lies east of W ¼ Corner fence N-E-W general miles below field level.

Good relocs on Monuments

40.00 set ¼ set post in ground with trench, pits, charcoal stakes, & Orange Orange scribe W. E & S. M.

July 1857 John B. Fellows Fg. 27 No. 43 used ¼ Cor. ⅛ south 20 chs., Prop Cor West 14.84 chs. then 24.84 chs. to Cor Sec.

1/4 Cor. 16-17, Cascade, 107-14 #741606 (1)

2-23-84, 1/4 Cor. 16-17: Fences now gone and corner in cultivated field. Found CIM down 12" with top section broken off. Corner 120'± East of large cottonwood tree (paced) and in line with short portion of fence running West (300'± West)