5—9-1969 set CIM by line of 1/16 & 1/4 cor east. #1
over ½" x 18" pipe

section corner. 17-18-19-20 Cascade 107-14.
10-1877 Hunter P321 no 315 S19. D Roorman #141705
Conrad Cuper.
found mound pits plain center road with
stake in center - no mear.
West side N½19. 39.90 - N-S ¼ line N½19. 39.96. both straight,

---

6-1892 Thos Fraser P489 no 464 S17 & 20 Iron Bowl.
found stone boulder claimed by J W Right Frank Yomans
as set by him in place & org stake. P321. Thos Crawford.
-16 east found 2 stakes close together on direct line
To past found as S¼17. 1½ lks longer on east side
each 19.97 (1318' then 19.98½ (1319'

5-1969 J Kerr.

found 1/16 stakes exactly as recorded in line fence E and S. at 1318' from center road at SW 17. claimed P 489 to be on exact line. as S 1/4 17 agreed under fence and local farmers born here agree fence line unchanged and small stake (lying down found at S 1/4 17 at 2637 accepted fence line as N-S. bearing SW 17 10' south of fence west. where C/M set. - 16 fence north about 1345' running west 1/16 fence east 2' N. dug 12' long in center road found nothing. old road 14" down old clay just under old road. assumed corner meeting - set C & M over 1/2" X 18" pipe in center road.
- meas east 1/16 1318 - 1/4 C/M 2637.
- meas north to 1/4 17-18 set M & L. 2639.6.
- meas south to rod in E black top 2627.85.

Card No 2 for RPS.

#741705 #2

Card no 2 17-18-19-20 Cascade

107-14.

C/M set. over ½" x 18" pipe in center road.

Blaze in power pole # 21871 SE 39.9.

E14-20-18.0-1.0

- Blaze in corner post 10' north & west 38.6.
- Center 36" burr oak near farm house NNW 208.0.
- Center 2 metal telephone terminal box NNW 135.3.

M+B - 1973± Elec. Comp. Meas. East 2636.80 To ¼ Cor. CEM

1936 Cont. D. B89. 75 P
found pointed boulder on center two-pod.

RPs Maple NNW 92.5
Oak W 38.0

Gov't Notes rec. Karick 1855
50.00 Sec post to corner to
Sec 7, 17-18-19-20. Erected mound
with 4 rocks. pits, charred stake
& Orange Orange scribe at each
angle

July 1857 John B. Fellows Pg. 27 No. 43 used Sec. Cor.
1/16 East 20 chs M&L to 1/4 Cor.

2.13E
2.5150
2.13E
2.44S

July, 1857 T. Hunter Pg. 36 No. 57 Shows Sec. Cor.
1/16 East 19.80 chs. M&L to 1/4 Post.

#741705 #3

Section Corner 17-18-19-20 Cascade 107-14

2-14-84 Sec. Cor. 17-18-19-20: Found CIM 2.0 deep in center of N-S road. Road too soft to set new CIM, but set 3/4" re-rod at road surface for temp. corner. LRP's } E 2.18 } S 2.44