5-9-1969 set C/M over ½ x 2' rod stone glass etc. (1)

¼ corner center 17 Cascade 107-14.
#741709

7-1857 J. Fellows. P27 no 43 & 17.

set corner inters lines.—

Meas north	39.54.	(2609.6'
Meas south	40.36.	(2663.78'
Meas east	39.88	(2632.08

(Fellows Broke Down All 4 ¼ section in this survey.)

6-1892 Thos Fraser P489 no 464 & 17 & 20 Town Board. 4 Yorranc. 3 Crawford found poplar & oak stake set by Mr Bell. 15 years before. still in perfect condition as in march. (history unknown).
—16 east set stake. 19.80 ¾ (1306.3

— over —

5-1964 J Kerr
Run west line S17 set corner M+L. 2639.6'
Run N-S 1/4 line S17. 5260.1'
Run E-W 1/4 line S17 aerial
set C/M over 1/2" x 24" reinf rod stone boulders glass etc.
set steel post up 4' from south of corner.
- corner comes near bottom of pond duke slope.
- east of pond overflow outlet (about on same level)
1264 1/4 - east to E 1/4 17. M'Ellis 2612 ±
- meas north to N 1/4 17. 2649.2
- meas south to S 1/4 17 2640.7

1/16 line only each set rod 3' east of west edge road on fence lines (Littlewood) 23' ± to center each end road culv
33' ± to main corner post east - north of fence west.

#741709 (15)

Center 17, Cascade, 107-14

2-1984, Center 17: Computed Int. 1/4 lines and dipped. Got slight dip 2'± North of comps. loc. Corner in pond dam on golf course. May be very deep or knocked over