6-7-1972 set C/M over. ½" x 18" rod. (1)

-711487 SET 1" P²/CAP RISER #741806

¼ corner	W¼ 18	cascade	107-14
	E¼ 13	Kalmar	107-15

1-1890 2has Fraser P445 no 430 S 18-19

Corners at W¼18 and NW18 could not be found. NW18 in 4' road cut so recorded stone gone lately. those who might have knowledge of W¼18 away. so did not establish either corner.

-1/16 south some sort of corner set as property line east to stone 5x10x24 set 19.95 north of S¼ 18 in line with N¼ 18. (a stone 4x11x24) found and set by Berry. S¼18 fence corner post found marked as corner. (over)

1967- terrane & road shape not very favorable to any possibility of any survival & corner if ever there. would require running in on town line

---

Co Hwy Dept B89. P76 1936.
boulder. set 2x2x18 near.
Maple west 27.8 F post L.W. 36.0.

6-7-72 Co surv- stump & maple still in place near 4' dia found boulder ± 8x10x14 not set real vertical and just & hub set above. - don't believe boulder ever set as corner but there is no road left so accepted same as corner until proven otherwise - believe big tank in Sec line.
set 1/2" x 18" rod below C/N. Corner 3' W C Line ±
134.6 NNE to hard nail & block in W side PP 24083 (1" S. Ch Wire
100.0 W To 1/2" x 2' rod up 1" just south & 5 bars Wire.

1/4 corner bet 1/4 is Calvert 107-14
E 1/4 is Kalmar 107-15

#741806 1 (2)

Cook Mills,

9000 Sec post + short channel stake E- 1/4
Section corner. Built mound + dug trench
Planted SE Cedar Corp., + NE Mark and.

T/14/87 PD CIM DOWN 14" AND IN NEW B.T, ON N-S TWP RD 3' WEST OF E. SET 1" SQPIPE/CAP AT RD SURFACE AN OVER CIM. CORNER IN LINE WITH FENCE WEST.