#741905 (1)

10-9-1963 reset 7-28-1966 C/M one ½" pipe.
6-12-70 C/M burden again set ½" pipe.

section corners. West 19-30 Cascade 107-14.
East 24-25 Kalmar 107-15.

8-1859 Hunter P36 No 58 N½ 30
used corner
set 1/16 east 17.78 then 20.00 to N¼ 30.

10-11-1877 Hunter P321 No 315 & 19 Norman, C Eager.
found old stake center road on line fences east & west.
- meas east 37.72. To old stake remains.

April, 1863 P.C. Compton Pg. 82 No. 103 Shows Sec. Cor
See Survey for breakdown of sec. 25 Rev.

some where in the interim a stone was set and lath found in center road in line fences E & W
10-1963 set C/M over pipe.
spring 1966 area became spungy & corner wrecked & broken
road repaired and new C/M set 7-28-66. over old pipe.

Rec. fence post E 40.61.
" " " W 33.68
Nail in hub on NE side 24" pine NW 130.3.
Corner lies 42.09 east of nail in top of brace post west
on transit line of rail and exact surface edge of chain
in post east. (for resetting corner).

#741905

(2)

Card # 2 West 19-30 cascade 107-14
east 24-25 Kalmar. 107-15.

Co H D 1968 B 335 found C/M broken again
corner is P.I. Δ 0° 9' 20" Rt going north Sta 237+39.25
Mear south 26 37.5 north 2634.54

6-12-1970 Co C/M again reported broken, found top broken off and gone, removed found. 1/2" rod below nail pipe, must have changed when corner broken before or rod is riser. checked all ties perfectly. did not reset C/M, set 1/2" rod x 2' - set 3/8" x 30" rebar west 100 feet, this rod came on exact line west edge 4 ch steel post ⊥ up 2" lines post at base only - as road will eventually be graded all C/M will be removed later.

6-1936 C.H.D. Book # 81 page 24 Found limestone
Monument 1' North of E-W fence line
1937 CHD fd limestone mon. (6L-89)
Gone Rpts 18" pine NWW 99.90' corner post West 33.7'
Set [illegible] post & stone adjacent with cross
scribing 19-24-25-30 Built mound & dug
trench. Found N.E. Cascade Range, &
N.E. Apple Orchard.

10/9/84 CORNER IN RD CUT. FD 5/8" IRON 100.00 WEST (1970)
SPIKE IN NE SIDE LARGE PINE 130.3 N.W. (1963) - SPIKE
GROWN OVER AND HUB NOW LYING ON THE GROUND. FOUND
NO OTHER GOOD RPs REMAINING. UNTIED POINT FROM
THESE TIES AND TOOK LRP } N 2.34
E 2.155
CALL PT FOR CASCADE INV.
FD 60d @ B.T. SURFACE } N. 2.10
E. 1.95
FD 30d beneath B.T. } N 2.2
E 2.0
FD 5/8" X 18" IRON 11" DEEP } N. 2.21
set corner here } E 2.07

130.3
-2.34
127.96
2.21
130.17

E-W 102.16
5/8 rod -2.07
100.09
To West
to rod

POINT IN LINE
WITH FENCE E & W