9-6-1963 set C/M over page. #742105 (1)

section corner 20-21-28-29 Cascade 107-14.
6-1892 Chas Fraser P489 no 464 L17-20 F Yoman.
found corner post which Mr. Elsworth J Crawford.
Town Board.
area was set at site of original corner.
- 16 north set 18" long irregular limestone M&L.
19.91 3/4. (1314.55)' Not found by Kerr in 1960

1960 J Kerr B81 P32 L21 Prec. Instruments.
run line NW cor 21 to SW cor 21. a recorded straight
line with 3 stones not equal dist. apart.
from NW 21 1313.4 - 1313.4 - 1314.55 - 1314.55
actual 1314.9 - 1314.9 - 1315.6 - 1315.6 over.

on digging at line and meas from north found wood standing down into clay set 1¼ x 42" pipe as corner. 9-1963 set CIM over 1¼" pipe below plow. Corner comes 4' north east-west farm boundry fenced - no north-south fences (common land) clothes line on wires opposite corner.

11-24-71. Cloth on wire gone - put on new one 2nd top wire steel post with lath & license plate wrapped around bottom post south. 4' - CIM fully 12" deep - will meas west.

2-7-76 Found top 6" section of CIM had been broken. Removed and left remainder as corner. Corner now 18" deep.

Govt Notes on Karrick 185-1/2 to south 20-21-28-29 80.00 set post for corner 10 south, chained 5 links in around ends with trench, drill, chained 5 links Orange Orange strobs at each angle

Section Corner 20-21-28-29 Cascade 107-14 ②
April, 1858 T. Hunter Pg. 52 No. 75 Shows Sec. Cor.
1/16 west 19.50 chs. m&L to 1/4 Post. #742105
(See Survey for breakdown of North 1/2 Sec. 29).

June, 1863 P.C. Compton Pg. 74 No. 108 Shows Sec. Cor.
used to Set 1/4 Cor 20-21 m & L. See Survey For
Interior of Sec. 21

June, 1863 P.C. Compton Pg. 75 No. 109 used Sec. Corner
For Subdividing S.E 1/4 Sec 20

Nov, 1863 P.C. Compton Pg. 78 No. 117 Shows Sec. Corner
used to Set 1/16 East m & L to 1/4 Cor 21-28

2-21-84, Sec. Cor 20-21-28-29: Set a survey marker sign & post
3.4 South of CIM found 1½' deep at edge of plowing and
4' North of E-W Fence.

5/26/1863 P.C. Compton (Pg 70 No 100)
established corner, no measurements
shown