Corner falls on M.H. Cover in intersection of 18th Ave and 33rd St. N.W. — Use notches cut in MH ring and intersect them to locate point for corner

1/4 Corner Center 22 Cascade 107-14 (1)

(over) See T. Hunter BK 5 P.102 Notes on Sec. 22 #742209

~~No record~~.

1941 J Kerr B 24 P 77 S 22 Sam Allen.
Ran N-S 1/4 line after setting S 1/4 and finding N 1/4
and E 1/4 and setting temp W 1/4.
set corner later destroyed.
- meas east 2638.57. - (2637.60 E Tie. 1975 Co. Surv.)
- meas entire N-S 1/4 line 5299.4.

6-1947 J Kerr B 34 P 58 S 22 J Weik
run line center north to North 1/4 22. set point
midway for lot survey at 1324.9 total 2649.8 (over)

Corner torn out by sewer line.
Corner in manhole. Can be replaced or may now have positive references by McGhee.

– 5-1870 Perry P 178 no 189 NE ¼ 22 Boardman Evans.
set stake utters lines - east 40.09 N. 40.19

Chisel marks in manhole ring (J. Kerr BK 87 P. 36 8-9-1963

top center hydrant	NW	45.43
Sp power pole.	SW	43.63.
5/8" iron block corner pin	NW	50.57.

B 340 Co H D 1968 RPS to 1/16 corner north (new 22).
iron pipe in place. - Sp in street light pole NW. 46.59.
Sp D in power pole SSW 123.98 → (iron over limestone)
Meas. east to 1/16 corner on N-S 1/16 line to 1/16 betw NE 22 and 1/4 22-23. 2638.24'