8-17-1963 set C/M over iron, orig stones nearby OK.
#742404 (1)

1/4 corner 24-25 Cascade 107-14
4-6-1876 Hunter P300 no 295 S25 R Smith, H Mizinger
Corner completely gone. reproduced line from center 25
over 1/16 north found survey P56 no 82. and doubled mear.
20.03 and set marked stake.
Mear east 39.66. (2617.56'
-16 west set stake M&L 20.24 (1335.84'

8-1876 Hunter P303 no 298 S24 H Dodge, R Smith.
found stake set P300 and 1/16 west.

12-1900 H Fraser P700 no 616 S30 107-13 E1/2 25
107-14
used stake just west 4 cor post, Geo Webb ~~[illegible]~~
which agreed with line from 1/4 cor south one 1/16 north.
-16 east set stone and stake by doubling line from 1/16 corner

east ¼ center 25 over 1/16 north 19.93½. 1315.7.
which also proved line & midway N¼25 and NE25 which was
19.78 (1315.48'

B 71 P11. 1962 corner shows 4X12X12 limestone
west 2665.7.
south 1319.41 M&L to iron set - RP 30.3 NW center 15" oak.
also shows N-S 1/16 line east ¼ center oak stone set midway.
1315.7.

B71 P78 - 8-1962 shows C/M at ¼ 24-25
shows limestone found east at 1303.5 - set ½" rod by stone.
shows 5/8" x 6' rod set in boggy land as section corner.
at 2607.0
shows stone found south ¼ above 1/16 on N-S 1/16 line
at 1314.92 with ½" rod just southwest ¼ stone.

Set C/M 8-17-1963 - corner lies 2' east ¼ line & under E-W fence.
Center Blazed Oak in fence E 118.4 - Center blazed WO S.S.W. 30.7
Nail - 8" Elm or Box Elder NNE 13.6

#742404 (2)

Card # 2 1/4 24-25 Cascade. 107-14.
12-1-1961 JKen. B 83 P 35 SW 1/4 24 F Sehl.
used iron at SW corner 24. (CIM set 9-1963)
ran and meas line east to limestone at 1/4 24-25.
(CIM set. 8-1963). set 1 1/4" pipe at 1/16 for line north
M & L 1332.85 or 2665.70 for the 1/2 mile.
Center Hwy 63 at that time 803.2 (no known RPs To 1/16)
- ran line north from 1/16 pipe to 1/16 on N side of SW 1/4 24
a corner set M & L 1331.22 or 2662.44 for 1/2 mile.
set property corners at 1/16 1307.8 M & L. then at 1634.75
forth for lines east then at 1961.7 for line west 653.9 from N

Sept. 1958 T Hunter Pg. 56 No. 82 shows 1/4 Post
used for breakdown in N 1/2 sec. 25 (over)

2-16-1976 Found CIM ~~pipe~~ in line with E-W fence and 3' E. of N-S Fence however all wire now on the ground and corner post knocked over.

Took R.P. : Spike in NW side blazed 8" Elm NNE 13.66

2-17-1976 Found Iron bar beside a stone at the 1/16 East. Corner appros 30' West of fence South and in line of E-W fence

[illegible] 40.00 set [illegible] 1/4 steel post West on true line between sets 40.00 set 1/4 steel post in mound 24 links with [illegible] 6 links chiseled stakes S 5° 32' and Orange Orange sets NE 15.44

#742404 (3)

1/4 Corner 24-25 Cascade 107-14

11-26-84

1/16 East of 1/4 Cr 24-25: Found 3½" thick pointed limestone filled with ground. Stone splitting. Drive concrete nail in top of stone for shot. There is a ½" rebar at the SW Cr of stone .10 So & .15W of nail. There is a T-bar with disc #10942 .4-7 S and .22 West of the nail