9-21-61 set C/M in hedge row under north-south fence midway between E 1/4 30 and E 1/4 31. #742905 (1)

section corner 29-30-31-32 Cascade 107-14

No records - no Hunter railroad notes on corner.

10-1961 J Herr B 84 P23 & 31 J Hennessey.

No inkling of idea or knowledge where corner could be. Common land on both east and west. - Did not find or use in Survey. 1921 for St Francis enters & 31. - could not re-find 1/4 30-31 used in 1921. so measure line carefully from limestone at E 1/4 31 north to E 1/4 30 5244.24 as there never was any 1/4 29-32 (30-31) set C/M. midway under N-S fence which is also enormous thorn hedge. fence lying on east side of hedge Mag or Magnet, betrue (over) line.

Corner placed slightly west of actual fence. about 1 foot
- Cut away hedge for line work - set limestone against
C/M. - Nail in fence - cloth tied on wire.

11-1961. B84 P41 S32 Franke, Sally
Meas south to ℄ road. 707.41 for property corner.
Then 1914.71 To limestone 1/4 31-32. total 2622.12
AZ ℄ road northwesterly 281° W of S31 using N-S line as 0°
AZ ℄ road southeasterly on S32 180 " "

B84 P24. set up ℄ road northwesterly at AZ 281°
RP rod 707.41 S NE31 - Sp 20" oak S 74.0 - S PP W ℄ S. 30.17
Sp tele pole NW 38.5 — line at AZ 281° 976.0 set iron.
RP TO NE cor barn SW 79' - disc tele pole NWly 88.8
— then 440 to rod RP Sp tele P NNW 72.0 - Sp PP WSW 80.0

Cascade section corner 29-30-31-32 (2

80.00 sec section post in corner
29-30-31-32

Bur Oak	10	S	36	W	73	#742905
Jack Oak	8	N	45	W	45	
Aspen	7	N	47	E	22	
Bur Oak	10	S	30	E	36	