~~10-9-1963 set C/M over rod. (found)~~ #742909
Note: Removed Jan 12-64 — see below
1/4 Corner. Center 29. Cascade 107-14.
H-1858 Hunter P 52 no 95 S 29.
show corner on plat. not how or when set.
- meas east 38.86 (2564.8 (rounds fishy)
- meas west 19.91 (1315.06' M&L
- 16 rock. prop corner. meas from ↑ E 19.46 W 19.96 N 19.56
corner accepted as correct (1284.36) (1317.32 (1289.64)
mutil proven otherwise
Hunters Tie To ℄ Railroad 989' To ℄ tracks.

(over

10-1963 found 3/4" steel rod. used by state and private surveyors - if 1/4 29-32 never found. Corner could be questioned. - set C/M corner rod found. accepted until proven otherwise.

M N D disc	power pole	SW	49.23.
"	cor fence post	S	35.3
"	" " "	N	34.7.
disc	tele pole.	NW	54.9.

Corner likely lines with fence running north & south.

~~Feb~~ Feb 12 1974 Removed the C.I.M. set there by T. Kerr. Because of the frost we were unable to remove the rod which is below the C.I.M. - Also the very base plate of the C.I.M. are still in rock about 2' below the road surface. will reset corner at true intersecting lines

M + B Probably set something at this Center

2-1984: Dug and found rock but got nothing.