X SW 31 Cascade #743105 (1)

section corner township corner.

SW 31 Cascade 107-14 - SE 36 Kalmar 107-15
NW 6 Rochester 106-14 . NE 1 Salem 106-15.

2-1882 Hunter P 375 No 366 L1 Hinds Bros.
found engraved mon set in 1879 by law.
- Meas west 16.65½ to prop corner then 23.31½ to ¼ cor
set by aver of 4 Hinds Bros as to location from cedar post.

4-1902 Armstrong P 34B L1. John Monahan.
found stone mon. P 375.
- Meas west 40.04 To stake found in line fence south.

- after paving put in 1931 a cross was cut in paving 2' south & paving by state reference.
this is accepted corner
- south ½"x24" rod driven in road on town line south at 1667.35 - lies 23.95 west of Carl Franke. steel light pole.
- 1/16 north set rod in road on town line 1315 south of E ¼ 36. Sp Cedar Fence post N.W. 39.0.
" " " S.W. 32.1.

Co Hwy D. 1968. B335 P.I. found cross in pavement 2.65' south of center line old 14 pavement
Sp 19 in F.P. N.W. 46.82, Sp 20 in F.P. W.S.W. 38.29.
Stone R.P.s are to rod, south of hub cor in line of rod described above by Carl Franke 110.00' south hub cor.

#743105

(2)

Card #2 township corner SW 31 Cascade.
NW cor 6 Rochester, SE 36 Kalmar, NE 1 Salem.

6-9-1970 Co surv referenced cross in pavement before const work on highway

– cross cut near south end 30" road conc curb	SE	37.44
– " " " north " " " " "	NE	39.09
– old disc on SW side wood cable term pole	SE	56.06
– " " " NW " " " "	SW	58.10
– center hole in 3" Hwy mon. Sta 338+79.5	SW	60.12
– " " " " " "	NW	64.28

cross 2.65 south center pavement
SE corner ele control box (6-22-72) NW 125.55

6-30-83, SW Cor 31: found P.K. in blacktop overlay on P.R. 34, 2.65 South of ℄ and in ℄ C.R. 164 N-S. No good RP's left to verify correctness so cut out blacktop with jackhammer and found recorded cross in concrete pavement below. PK was not cross. Drilled hole through concrete and drove 5/8" re-rod with cap as corner.

RP: CHD Plastic Disc in pp NE 78.10

SECTION CORNER TOWNSHIP CORNER (3)

SW 31 CASCADE SE 36 KALMAR

NW 6 ROCHESTER NE 1 SALEM #743105

6/4/92 County Surveyor Fd 5/8" rod cap missing. Set 1/2" (ref rod) Rp's 20.97' west to nail & bottle cap in PP 52403 25.0' EAST to E of CR rock. Pt south of CR 34

~~R~~@ ref rod ~~R~~RT SE 36 to top of red light KROC radio tower

63° 36' 23"

To SE 36

VA 88 36 51 dv 04

SD 184.74 HD 184.685

Jackhammered out conc so mon can be set back after road work.

7-12-93, Set 1" Sq pipe w/cap as corner in CR# 34
2.65' South of ℄ & in ℄ of CR 104 North & South
R.P.'s
Plastic disk in P.P. NE 78.29'