9-20-1963 set C/M over orig stone #743305 (1)

section corner south 32-33 Cascade 107-14.
North 4-5 Rock 106-14.

5-1875 Hunter P272 no 270 S 5 F Stoppel.
found stone in center road in line fence north.
- mear south 39.34.

10-1894 H Fraser P554 no 511 S 32 L. Fidtach, A Engle.
found stone center road placed survey section 5.
-16 west set stone and stake N & L 19.88¾.

10-1892 H Fraser P495 no 468 S 4 Hansen & Waldron.
corner could not be found until mear from NW cor 5 to N¼ 4.
and S W cor 4 to W¼ 33 in setting new stone found old stone in
center road with wood & small stones - ~~set ¼ stone~~ (over

sandstone with cross on fencerow used for grade since U.S. 14 built in '30's road further south at this point.

9-1963 set C/M over stone

- Elec power pole W 5.5'
- corner lies 1.5' north of east-west fence.
- no north south fence.
- lies considerable west, several hundred feet of main entrance Country Club Manor.

T. Fraser 1891-1892 unrecorded Survey in Sec 4-106-14 T.F. Book 8 p. 32-35
Set Stone running To point ~~on Turn line~~ and 1/3 of 1½ miles from S¼ 33 To 1½ miles W.
Set Prop. Meas. N-S

P495 set stone 4x8x24 at 14.82½ east NW cor 4.

#743305 (2)

Section Corner South 32-33 Cascade 107-14
North 4-5 Rochester 106-14

May, 1857 Thos. Hunter Pg. 23 No 37

Caption of April, 1886 Thos Hunter Fd Stone in Center of Road. used to set ¼ Corner 32-33 M & L. Meas. North 80.31 Chs. to Sec. Corner.

Gone N.W.S - Set a new post + stone chiseled for corner common to 4-5-32-33, both witness trees.

10-9-96 Fd CIM on SW side white plastic post but PK W 5.5' now gone. Put CSD in N side new PP E 4.09 Also SW Cor house Fdtn NNE 73.32