10-7-1963 set C I M ones 1/2" pipe #750405

section corner 4-5-8-9 Kalmar 107-15 (1)

6-1900 Robt Fraser P684 No 608 S 9. Brooks, Haugerson found 2 stones side by side and old stake on west side. some controversy that corner had been moved west but B T remains and other details proved corner correct

---

7-1910 Chas Larson P132B S 8-9 Haugerson, Carlsen. found 2 stones P 684.
-1/16 south found stake, set new one M & L to 4 8-9
a gas pipe set. P684

10-1960 J Kerr B 80 P57 Rundell. (Orig
found stones set large pipeat corners and as witness

10-1963 J Kerr used corner set C/M over piece of 1/2" pipe.

Roger Brand

3' angle iron E 27.0 Core 7-7-95

Sp power pole. NNE 148.9

" Stub Pole – W.N.W 42.2. Core 7-7-95

Center 30" elm S.S.W 107.7. Core 7-7-95

Corner lies 9' E. of ℄ Road on Curve & 2'Sa of fence East

& in line ℄ Driveway To west

fence gone 7-7-95

Gov't Notes Kennick 1954

80.00 Set post for corner to seek 4, 5, 8-9

Sugar 20 S 50 W 69

Hickory 7 N 40 W 34

Elm 22 N 40 E 81

Sugar 20 S 64 E 41

#950405 (2)

Section Corner 4-5-8-9 Kalmar 107-15

Dec. 1856 Thos. Hunter Pg. 20 No. 32 shows Sec. Cor. meas. North 39.89 chs. to 1/4 post with two prop. splits at 10.09 chs. the 14.90 chs then 14.90 chs. to 1/4 Post.

7-7-95 Corner found by Roger Brand and associates. Typ of CIM Mother off. Ca 10" deep in ground

Center of 18" Pine (SW) 58.3 feet

Center of Telephone Box (W) 55.7