Aug 1974 Co. Surv. Set ½" rod as corner.

Section Corner 5-6-78 107-15 #750505

Gov't Notes

Set Post for corner to sections 5,-6-7-8

Ironwood	8"	S 22° W.	14 lks
Sugar	18"	N 83° W.	58 lks
Walnut	16"	N 8° E	42 lks
Elm	15"	S 18° E.	68 lks – Accepted as B. tree (1974)

Land rolling + second rate

Timber Aspen + Oak

Aug 1974 Co. Surv.

Corner falls in a very wet area, Springs all over. Impossible to dig for corner.

Ran traverse (electronic) to corner Location to try + isolate corner. Found all fences Led to a Large elm. Used Elm AS a Gov't B. tree. + with transit compass we established point. Also check govt distance to a creek 0.7 chs. (46.2') North Checked within 1 ft.

The lost position of the corner if set by double proportionate measure would place corner 8' west - 15' North of our point making A Larger Kink at 1/4 cor 5+8 AS line from N.E. 8 over N 1/4 8 already falls South. Accepted large elm (± 40" dia) AS Gov't B. tree - set corner

R.P's		
Spike in maple	S S W.	23.5'
Spike S side walnut	W	14.92'
Spike W. side Elm	S. 18° E.	45.1'