Note: Corner Probably No Good

10-12-1965 set CIM over ½" x 2' rebar ①

According to 1 Ky. [illegible] survey [illegible] found a stone

3-22-77 Set CIC "Correction of Corner"

1/4 Corner T-18 Kalmar 107-15

#'150'104

2-1871 R Perry P145 No 171 Sec 7

extensive work done in area of Center sec 7 where stake found with 2 bearing trees with many points proven by this unrecorded, unknown survey and N ¼ and E ¼ sec 7 No mention of W ¼ and S ½ 47 to prove corners used - Center ¼ finally set 10-1964. 65' south, 35' east of apparent center 7 used in 1871

4-1897 H Fraser H Fraser P607 No 552 Sec 7

" Could not find any stake at this corner, John Hoffman but Mr. John Huffman and others said the stake Cover

stood close to north side of corner post of fence!
No meas or line any direction. set nothing

11-1938 J Kerr B 14 P 13 S 7 Rahm Survey
ran and meas from SE corner 7 (7-8-17-18) west
(corner not described) found S 1/4 7 (1/4 7-18) "a stone set on
the north side of old fence corner post meas 2629.3
12.4 E to center blazed 24" red oak
33' slightly E of N to blazed 18" wh oak (S & E of fence)
(worked on plats on E 1/2 of SE 1/4 section 7)

11-1947 46 J Kerr B 32 P 43 S 7 Twin Bor Co.
ran S 1/2 of E line Sec 7 rough survey P 41 2695.56 than E
P-43 plat of sec 7 shows 2629.3 from S 1/4 7 east.

for dist S 1/4 7 See Card #2.

Card # 2 1/4 7-18 Kalmar 10 7-15. (2)

Cont- 11-1947 JKen B 32 P43 #150'704

" found fence post set in place of stone at S 1/4 corner of section actually 36' N of true corner did not dig for stone, ran line north to N 1/4 cor also fence post line fell 60' W of N 1/4 cor".

- Mean of 2659.3 on plat at S 1/4 7 to center 7 Ont also E.P. To 2628.35 Can see between that meant. also showed 2630.32 from 1/4 pipe set at center 7 each to E 1/4 cor 1871 2615.06 1964 2636.85 so no corner position in this survey

over.

1964 JKell B 89 P 58 Kalmar twsp.
Ran S line sec 7 very carefully - meas E 1/2 twice.
set C/M on S 1/4 7 on line C/M over gun barrel at W 7-18
and pipe at 7-8-17-18 meas E 2645.78
west 1322.84 to pipe set on 1/4 then ~~1256.17~~ 1256.7 to Sec Cor.
See W 7-18 - ran & meas line from pipe set at N 1/4 7
in place of old stake found near corner post where
- set Center 7 where E-W 1/4 lines intersected See Center 7
set C/M over 1/2" x 24" rod.
95.0 ENE to center burn white oak
49.8 S 2 E to dice in power pole
26.0 S W to center 18" white oak
Corner 5' S old fence running E - 7.5' W of good fence &
Meas N 2659.0± to center 7 then 2570 to N 1/4 7 R2504.7

¼ Corner 7-18 Kalmar 107-15

#750704

3-11-77 Intersected lines from Kerr pipe at the N. ¼ Cor 7 over Kerr pipe at the Center 7 and from West Section Cor 7-18 over Kerr pipe at the 1/16th East. The point came approx 14' East of Kerr C.I.M and approx 2' East of the corner post to fences North and East. Dug to clay from the point 2' North, 6' South, 2' East and 2' West to the corner post. Found nothing. Condition poor. Also dug a small hole on line and at prop. Dist measure from the N. Sec Cor 7-18 over possible 1/16th stone found at the 1/16th East. Found nothing.

3-22-77 Set a C.I.C 1/36" p² as the corner at the

intersection of the line from the N 1/4 Cor 7 (Kerr pipe) over Center 7 (Kerr pipe) and the line from SW 7 to SE 7 (actually used line from SW 7 over Kerr CIM at the S 1/4 Cor 7 since Kerr had set the S 1/4 Cor 7 on line) Corner came 13.76 East of Kerr CIM (removed).

R.P.'s Spike + CSD SW side 18" Black Oak SE 31.39

Old CHD Dia E side pp #27063 S 49.0S

CSD S side corner post WNW 2.13

3-11-77 Found Kerr pipe and also a possible 1/16th stone (16") 7/16 by 3 1/2" thick 2.0 South and 4.8' E of Kerr pipe. Stone 1' West of the N-S fence on the West side of the road.

Kalmar 1/4 corner 7-18 #750704 | 4
Gen'l Notes Kansas 1854
40.00 set temp 1/4 steel post
East on true line between steel 7+18
39.00 set 1/4 steel post
Asplan 6 N53 E-58
" " 6 N54 W48