X 11-22-1960. 8-6-70 set C/M over gas pipe set 6-1900 (1)
See note of B Dec
1/4 Corner 8-9 Kalmar 107-15 #750906
6-1900 Robt Fraser P684 No 608 S.G. Brooks. ~~Haugman~~ Hadgersen.
found old stake after running section line south
from NW Cor 9. came with 12 lks of M & L and on line.
drove gas pipe it came 65 lks east of west road fence.
9 links north of fence running west on east side of road.
- meas north 40.07 1/2 2644.95 42.9' old stake was 1 link north of
- meas south 40.09 1/2 2646.3 total 5291.25 - M&L.
1/16 south set stake 20.04 3/4 M & L. 2823.15

11-1960 J Kerr B80 P57 Randell. No Good
didn't look for corner didn't take notes of gas pipe
set 2" square steel hollow staff from old farm machine
at 2644.51 from □ iron to C/M at 4 ∠ 5-8-9. (over)

very securely set - couldn't be budged by 10 ton jack.
Spud power pole L L E 124.7.
Disc in treated fence post W N W 49.96.
North-south fence on west side of road W 49.0.
corner lies 7.6 south of fence running west.
" " 2.0 east of east edge road surface
in edge of ditch. proper place would likely bring it
near center of road. total mile 5289.02
- south set ½" rod on line as line west at 1222.25
~~Sp tele pole NW 73.6~~ Sp PP W ≠ S. 24.8
~~Center 6" pine tree E 23.3~~
gas pipe also found by Chas Larson 7-1910 and 1/16 stake N.
set stone 2x12x16 on line 40 rods west. see card #2.

#750906 (2)

Card # 2 1/4 8-9 Kalmar 10 7-15

6-23-70 searched for witness stone at cor 8-9-16-17 as corner recorded in ravine found likely stone 16.7' west of stone on east slope of ravine ~~accepted as corner~~ recorded 9.9' west. - suppressed iron pipe may still be in place at 1/4 8-9 3.4' west. - 8-6-70 Co surv dug with tractor for iron pipe found at least 1½" pipe 3' below road 5.65' west and 2.55' north of □ iron. set C I M cement block over pipe, glass, cans, trash of every kind - C I M down at least 8" on near exact line east edge of traveled road - measure now north 2642.0± and 2647.5 south. all indications are true SE cor 8 further north than stone used which lay .405' south E-W fence wire or 2643.0. corner recorded as 1 link north of M & L at 1/4 8-9. RPs (over)

- orig spud in power pole. (W side) #22792. SSE 128.03
- ½" x 2 re rod due west 80.0' rod line 4½' south of E-W fence, a poor fence, and 1.5' north of random steel gle fence post
- corner in line edge east edge of traveled road.
- corner now 43.7 east of fence wires running south (not north) record 42.9'
- Mean north line 2642.0 R 2644.95'
Mean south to E-W fence or line of witness stone 2643 ± R 2646.3.

7-1910 Ch Larson P 132 B claims set stone over hole filled with lime at location of stake found at 80 rods. Also stone over lime hole 40 rods south

orig post B tree S 60° W 11" elm 217 - 143.22 (tree there will check.)

4-20-71 found likely ¼ corner south recorded as stone over lime hole found some lime and dead stake. set ½" x 4' iron re bar with small ridges rather than like modern re-bars. stone on east side 3 x 7 x 12 ± and word on west side.

Card no 3 1/4 8-9 Kalmar & adjacent corners (3)

4-20-1971 cont Co surv. at 8-9-16-17. #750906
dug considerable area after again searching extensively
for possibility that witness stone found 6-23-1970 at
8-9-16-17. 16.7' west of corner used to set 1/4 8-9 in
11-1960 by J Kerr record 9.9' west or 6.8' west orig line
for true corner 1/4 8-9. 2.25 west of direct line
- using 1/16 iron set which came at 1322.9 south of C/M
at 1/4 8-9 and 6.12 west of N-S line run in 1960
- if witness stone was due west of 8-9-16-17 and corner
accepted in 1960 was 4.5' south of fence wire (fence line
very crooked) line total 52.89' in 1960 could be 5285 ±
- North 1/2 now 2644.5 - 2.55' or 2641.95' C/M to C/M
over

south ½ now. 5289 - (2641.95 + 4' ±) or 2643.05
from C1M at ¼ 8-9 To section corner ℄ placed in gully.
- M&L 1321.53 (1322.9 acceptable considering terrain
and fact that true N-S ℄ 8-9-16-17 not known.
- line ℄ 1/16 iron within .1' orig line 6.8 S and 5.65 at ¼ cor
making 6.22 against 6.12 corner could go .1 west
very acceptable as witness stone was not perfectly vertical.
RP to 1/16 iron as set Old line E 5.65 - 6.12 - 6.80

2" pipe 1' east ℄ N-S fence set by McGhie 2' S ℄ E 6.4'
orig spud. west side power pole almost exact N 74.15

John Kerr rod set at 1222.25 in 1960 re measured at 1224.7
from C1M and moved be east ℄ true line 6.09'
RP to rod. Orig spud on N side PP 6' W ℄ S 24.8.
Center 16" pine southerly ℄ row E 23.3

¼ Corner 8-9 Kalmar 107-15

#750906

12-5-75 (1/16W) Set ¾" x 24" rod at computed M&L location.
R.P.'s: Nail E side 24" Oak SSW 21.68
Nail N side 18" Oak WNW 14.90

12-5-75 (Center SE ¼) Set ½" x 15" rod at (comp.) intersecting 1/16 line & Corner comer in N detach of E-W road (29' N of ℄)
R.P.'s: CSD in most northerly post of Oxbow Park Sign WNW 77.77
CSD in pp # 22804 SW 88.74

Soil Notes Kerrick 1954
40.00 Surf 1/4 Surf P-SL
Elm 11 S CO W 49
Ironwood 7 S 68 E 45